

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005738/KPA3Q2**Date:** 18/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220004868
Claimant Vehicle No :	SMW9449E	Insured Vehicle No :	GBL7019P
Date of Loss:	11/06/2022	Nature of Claim:	TP
		Claim No:	3678452507SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW9449E		
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Engine No:	27186030355493
Reg. Date:	17/02/2012 (Man. Year: 2011)	Chassis No:	WDD2120472A547552
Colour:	Metallic Black	Odometer:	132610 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,351.70	185.40	2,166.30	92.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	400.00	250.00	38.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,001.70	585.40	2,416.30	80.50
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	16/06/2022	
Date Inspected:	19/07/2022	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	*Check	1,660.00 FN	*- FN
2	1		*FRONT BUMPER RH DAYTIME RUNNING LAMP	*Check	595.00 FN	*- FN
3	1		*FRONT BUMPER RH DAYTIME RUNNING LAMP CHROME	*Check	152.00 FN	*- FN
4	2		*FRONT BUMPER SIDE CHROME MOULDING	Necessary	206.00 FN	*206.00 FN
				Sub Total (S\$)	2,613.00	206.00
				- Nett Item Discount on N Items 10.00/10.00% (S\$)	261.30	20.60
				Total Parts (S\$)	2,351.70	185.40

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER & ATTACHMENTS GRILLE & REALIGN THE SAME	New	300.00	180.00
2	PUTTY & RESPRAY FRT BUMPER ,PARKING SENSORS & ALL AFFECTED AREAS	New	350.00	220.00
Gross Labour Cost (S\$)			650.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >