



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300777

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/02/2023
Reference CC6/CTI22005744/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SJB 3501Y
Insured Veh. SML 3142L
Claim No. SNM22D203934/C02
Policy No. DMPCSNW00163992102
Accident Date 30/05/2022
Inspection Date 01/06/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22005744/Apa3q2 Date: 10/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SML 3142L	Veh. Inspected	SJB 3501Y	
Policy No.	DMPCSNW00163992102	Coverage (\$)	0.00	
Claim No.	SNM22D203934/C02	Excess (\$)	0.00	
Assign From		Assign Date	01/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	RN61053724	Colour	BRONZE	
Odometer	204417 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	MICHELIN	6 mm	
L/H Front Tyre	225/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/05/2022	Inspection Date	01/06/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 3501Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BUCKLED	838.40	684.00
1	BONNET LOCK	DAMAGED	84.30	84.30
2	BONNET HINGE @\$64.30	BENT	128.60	128.60
1	BONNET INSULATOR	NOT NECESSARY	124.80	-
2	BONNET STOPPER @\$24.10	NOT NECESSARY	48.20	-
1	BONNET FRONTAL SEAL	NOT NECESSARY	98.40	-
1	FRONT BUMPER REINFORCEMENT	BENT	218.80	218.80
2	FRONT BUMPER SIDE RETAINER @\$53.10	NECESSARY	106.20	48.00
2	FRONT BUMPER FOG LAMP @\$213.50	CRACKED	427.00	427.00
2	FRONT BUMPER FOG LAMP OUTER GARNISH @\$98.40	NOT NECESSARY	196.80	-
1	FRONT BUMPER UNDER COVER	NOT NECESSARY	178.40	-
1	FRONT GRILLE LOGO	NOT NECESSARY	86.50	-
2	FRONT HEADLAMP @\$782.20	CRACKED	1,564.40	1,390.00
2	FRONT HEADLAMP LOWER BRACKET @\$74.30	CRACKED	148.60	148.60
2	FRONT FENDER @\$518.40	BUCKLED	1,036.80	1,036.80
2	FRONT FENDER INNER COWLING @\$156.30	NOT NECESSARY	312.60	-
1	FRONT SUPPORT PANEL	BUCKLED	520.40	520.40
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	98.60	-
1	FRONT BRACE PANEL	NOT NECESSARY	153.20	-
1	AIR CON CONDENSER	DENTED	894.80	894.80
1	AIR CON FAN BLADES	NOT NECESSARY	221.30	-
1	AIR CON FAN MOTOR	DAMAGED	390.50	390.50
1	AIR CON FAN COWLING	CRACKED	282.30	282.30
1	AIR CON INLET PIPE	BENT	184.30	184.30
1	AIR CON OUTLET PIPE	BENT	164.60	164.60
1	BATTERY TRAY	NOT NECESSARY	256.30	-
1	BATTERY BRACKET	NOT NECESSARY	115.60	-
1	BATTERY COVER	NOT NECESSARY	98.40	-
1	WIPER WASHES TANK	NOT NECESSARY	246.90	-
1	AIR DUCT	NOT NECESSARY	189.90	-
1	RESONATOR TANK	NOT NECESSARY	204.80	-

Report Ref No. CC6/CTI22005744/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR	DENTED	1,365.10	1,365.10
1	RADIATOR SPARE TANK	NOT NECESSARY	176.40	-
1	RADIATOR FAN BLADES	NOT NECESSARY	211.60	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	354.20	-
1	RADIATOR FAN COWLING	DAMAGED	296.10	296.10
1	AIR FILTER HOUSING (ADDITIONAL)	NOT NECESSARY	145.60	-
1	AIR CON COMPRESSOR (ADDITIONAL)	DAMAGED	1,424.50	1,265.00
1	LH FRONT ENGINE MOUNTING (ADDITIONAL)	TORN	254.70	254.70
1	RH FRONT ENGINE MOUNTING (ADDITIONAL)	TORN	332.10	332.10
2	FRONT CROSS MEMBER (ADDITIONAL)	BENT	1,275.30	1,143.00
	LESS 20% DISCOUNT		-3,091.26	-2,251.80
			12,365.04	9,007.20
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER (SN)	DISTORTED	1,200.00	800.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	FRONT GRILLE (SN)	CRACKED	650.00	380.00
1	FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT NUMBER PLATE WITH CASING (SN)	MISSING	60.00	60.00
1	BATTERY (SN)	NOT NECESSARY	320.00	-
1	HORN (SN)	NOT NECESSARY	180.00	-
1	RADIATOR COOLANT (SN)	NECESSARY	120.00	40.00
1	AIR CON GAS (SN)	NECESSARY	100.00	30.00
1	BONNET INSULATOR CLIPS (SN)	NOT NECESSARY	40.00	-
2	FRONT FENDER TOP GARNISH CLIPS @\$20.00 (SN)	NOT NECESSARY	40.00	-
2	FRONT FENDER INNER COWLING CLIPS @\$50.00 (SN)	NOT NECESSARY	100.00	-
			2,920.00	1,370.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING.		1,400.00	1,000.00
	LABOUR FOR SPRAYPAINTING.		1,000.00	900.00
	WIRING CHECK.		800.00	30.00
	TO APPLY RUST PROOF/TUFF COATING ON ACCIDENT AREAS.		200.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR REMOVE & RENEW FRONT AIR CON CONDENSER / VACCUM & TOP UP AIR CON GAS.		150.00	60.00
	LABOUR FOR REMOVE & RENEW RADIATOR / TOP UP COOLANT.		150.00	60.00
	LABOUR FOR REMOVE & REFIX ENGINE (ADDITIONAL).		600.00	350.00
	LABOUR FOR REMOVE & REFIX FRONT UNDERCARRIAGE (ADDITIONAL).		400.00	350.00
	LABOUR FOR REPAIR & STRAIGHTEN BOTH CHASSIS FRAME (ADDITIONAL).	NOT NECESSARY	500.00	-
	TO CONDUCT WHEEL ALIGNMENT (ADDITIONAL).		150.00	80.00
			5,350.00	2,890.00
GRAND TOTAL			20,635.04	13,267.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,600.00

Report Ref No. CC6/CTI22005744/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJB 3501Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJB 3501Y

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJB 3501Y

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJB 3501Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

