



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2300976

INV Date 18/02/2023

Reference CC4/LPC22005748/Apa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJV 6345G
Insured Veh. GBC 9395L
Claim No. 22/22/22/VC05/025868
Policy No. Z22VC05010497
Accident Date 29/05/2022
Inspection Date 02/06/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22005748/Apa3q2 Date: 18/02/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 9395L	Veh. Inspected	SVJ 6345G	
Policy No.	Z22VC05010497	Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/025868	Excess (\$)	0.00	
Assign From		Assign Date	02/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WWWZZZ1KZAU001113	Colour	WHITE	
Odometer	151465 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/05/2022	Inspection Date	02/06/2022	
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 6345G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	TO REPAIR SEE LABOUR	1,502.70	-
1	BOOT LID LOGO	NECESSARY	117.07	117.07
1	BOOT LID EMBLEM 'JETTA'	NECESSARY	114.21	114.21
1	BOOT LID EMBLEM 'TSI'	NECESSARY	89.62	89.62
1	BOOT LID LOCK	NOT NECESSARY	194.71	-
1	BOOT LID WEATHERSTRIP	NOT NECESSARY	260.33	-
1	BOOT LID REVERSE LAMP LH	CRACKED	197.33	197.33
2	BOOT LID HINGE @\$177.33	NOT NECESSARY	354.66	-
1	TAIL LAMP LH	CRACKED	389.31	389.31
2	TAIL LAMP LOWER BRACKET @\$49.75	N/S CRACKED	99.50	49.75
1	REAR BUMPER (UPPER)	DEFORMED	1,007.30	1,007.30
1	REAR BUMPER (LOWER)	DEFORMED	674.31	401.00
2	REAR BUMPER REFLECTOR @\$70.95	N/S CRACKED	141.90	70.95
1	REAR BUMPER CENTER BRACKET	CRACKED	140.40	140.40
2	REAR BUMPER SIDE BRACKET @\$50.99	NOT NECESSARY	101.98	-
1	REAR BUMPER REINFORCEMENT	DENTED	698.51	698.51
2	REAR BUMPER SIDE RETAINER @\$89.42	NOT NECESSARY	178.84	-
2	REAR FENDER INNER COWLING @\$180.77	NOT NECESSARY	361.54	-
1	REAR END PANEL	NOT NECESSARY	961.33	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	207.15	-
	LESS 10% DISCOUNT		-779.27	-327.55
			7,013.43	2,947.90
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	BOOT LID SEALANT (SN)	NOT NECESSARY	150.00	-
1	SET BOOTLID INSULATOR CLIP (SN)	NECESSARY	80.00	-
1	BOOT LID 'BABY ON BOARD' STICKER (SPECIAL TYPE) (SN)	NECESSARY	80.00	20.00
1	SET TAILLAMP CLIP (SN)	NECESSARY	60.00	10.00
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	80.00	-

Report Ref No. CC4/LPC22005748/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	150.00	-
1	SET REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			1,040.00	260.00
	LABOUR			
	TO PANEL BEAT ,REMOVE AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF BOOT LID .		1,400.00	400.00
	TO SPRAY PAINT AFFECTED AREA.		1,200.00	400.00
	TUFF COAT.		250.00	30.00
	WIRING AND BULB CHECK.		180.00	30.00
	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR .	NOT NECESSARY	250.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	REAR CHASSIS ALIGNMENT.	NOT NECESSARY	250.00	-
	TRANFER BOOTLID MECHANISM.	NOT NECESSARY	80.00	-
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			4,020.00	910.00
GRAND TOTAL			12,073.43	4,117.90

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,300.00
---	--	--	-----------------

Report Ref No. CC4/LPC22005748/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 6345G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 6345G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 6345G

RE-INSPECTION

