

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005750/APA3Q2**Date:** 18/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800043466
Claimant Vehicle No :	GBG424A	Insured Vehicle No :	SLZ2820H
Date of Loss:	18/05/2022	Nature of Claim:	TP
		Claim No:	1333994420SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG424A	Engine No:	HR16082270D
Make & Model:	NISSAN NV200, 1.6 DX (A)	Chassis No:	VM20103113
Reg. Date:	24/05/2017 (Man. Year: 2016)	Odometer:	77959 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,749.39	4,698.50	4,050.89	46.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,990.00	1,860.00	2,130.00	53.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,739.39	6,558.50	6,180.89	48.52
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	12,739.39	5,200.00	7,539.39	59.18
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		5,773.45		
Global Sum Settlement (S\$)		5,750.00		

INSPECTION

Date of Assignment:	06/06/2022	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	06/06/2022 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	566.90 FL	*566.90 FL
2	1		*REAR BUMPER TOWING COVER	Not Necessary	86.00 FL	*- FL
3	1		*REAR BUMPER SPONGE	Cracked	145.89 FL	*145.89 FL
4	2		*REAR BUMPER SIDE RETAINER	Necessary	79.40 FL	*79.40 FL
5	1		*TAILGATE	Dented	2,080.40 FL	*1,737.00 FL
6	2		*TAILGATE STOPPER	Not Necessary	42.80 FL	*- FL
7	1		*TAILGATE LOGO	Necessary	67.50 FL	*67.50 FL
8	1		*TAILGATE NV200EMBLEM	Necessary	66.30 FL	*66.30 FL
9	1		*TAILGATE VENETTEEMBLEM	Necessary	68.50 FL	*68.50 FL
10	1		*TAILGATE OUTER MOULDING	Not Necessary	389.50 FL	*- FL
11	1		*TAILGATE LOWER LOCK CENTER COVER GARNISH	Not Necessary	235.50 FL	*- FL
12	1		*TAILGATE INNER LOCK	Damaged	271.40 FL	*271.40 FL
13	1		*TAILGATE LOWER LOCK	Not Necessary	26.40 FL	*- FL
14	1		*TAILGATE INNER TRIM	Not Necessary	368.70 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Cut	316.80 FL	*316.80 FL
16	1		*REAR END PANEL (OUTER)	Dented	598.60 FL	*598.60 FL
17	1		*REAR END PANEL TOP COVER GARNISH	Deformed	235.60 FL	*235.60 FL
18	1		*REAR FLOOR PANEL MAT	Not Necessary	1,219.80 FL	*- FL
19	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
20	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
21	1		*REAR BUMPER LOWER LIP (SPECAIL TYPE)	Deformed	250.00 FS	*180.00 FS
22	1		*SET REAR BUMPER REFLECTOR (SPECAIL TYPE)	Necessary	80.00 FS	*40.00 FS
23	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
24	1		*TAILGATE WRAPPINP (SPECAIL TYPE)	Necessary	800.00 FS	*350.00 FS
25	1		*TAILGATE STICKER 70KM/H	Necessary	50.00 FS	*15.00 FS
26	1		*TAILGATE STICKER 7PAX	Necessary	50.00 FS	*15.00 FS
27	1		*SET TAILGATE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
28	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
29	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
30	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
31	1		*REAR END PANEL (INNER) SEALANT	Not Necessary	150.00 FS	*- FS
32	1		*REAR SPARE TYRE	Not Necessary	500.00 FS	*- FS
33	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,435.99	5,113.89
- List Item Discount on L Items 10.00/10.00% (\$\$)	686.60	415.39
Total Parts (\$\$)	8,749.39	4,698.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND REPLACE PARTS	New	1,600.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	800.00
3	WIRNING ,BULB CHECKING	New	180.00	30.00
4	TRANSFER TAILGATE MECHANISM	New	80.00	60.00
5	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
6	REAR CHASSIS ALIGNMENT	New	250.00	0.00
7	REMOVE AND REFIX REAR REVERSE SENSOR	New	80.00	50.00
8	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
9	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			3,990.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >