

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIS22005752/ANY3E2

**Date:** 11/08/2022

### REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2001050680  
**Claimant Vehicle No :** GBL934T **Insured Vehicle No :** GBG6910Z  
Date of Loss: 13/06/2022 Nature of Claim: TP Claim No: 202222005207KC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL934T**  
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR (M) Engine No: 1KDB070475  
Reg. Date: 16/03/2021 (Man. Year: 2020) Chassis No: JTFHT02P500251494  
Colour: Silver Odometer: 136886 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,079.10	4,003.57	3,075.53	43.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	2,020.00	1,260.00	38.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,359.10</b>	<b>6,023.57</b>	<b>4,335.53</b>	<b>41.85</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,359.10</b>	<b>4,800.00</b>	<b>5,559.10</b>	<b>53.66</b>

### INSPECTION

Date of Assignment: 16/06/2022  
Date Inspected: 16/06/2022 Inspected At: Automobile Hub Enterprise  
1 Kaki Bukit Avenue 6  
#02-11 Autobay  
Singapore 417883  
Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Aug 2022)
<b>Parts:</b>	213	TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBL934T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	481.80 F	*481.80 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Necessary	131.60 F	*131.60 FL
4	1		*REAR BUMPER STICKER	Necessary	100.00 FS	*50.00 FS
5	4		*REAR BUMPER LOWER BRACKET	Bent	100.00 F	*100.00 FL
6	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
7	1		*REAR END PANEL OUTER	Dented	589.60 F	*589.60 FL
8	1		*REAR END PANEL INNER	Repair	645.90 F	*- FL
9	2		*TAILLAMP	Not Necessary	650.20 F	*- FL
10	1		*TAILLAMP LOWER APRON	N/S Torn	184.40 F	*94.20 FL
11	1		*TAILGATE	Dented	1,855.20 F	*1,855.20 FL
12	1		*TAILGATE LOCK	Damaged	275.40 F	*275.40 FL
13	1		*TAILGATE WEATHERSTRIPE	Cut	381.90 F	*381.90 FL
14	1		*TAILGATE OUTER MOULDING	Not Necessary	364.70 F	*- FL
15	1		*TAILGATE OUTER MOULDING CLIPS	Not Necessary	20.00 FS	*- FS
16	1		*TAILGATE CAMERA	Damaged	580.00 FS	*450.00 FS
17	1		*TAILGATE GLASS MOULDING	Necessary	172.50 F	*172.50 FL
18	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
19	1		*TOYOTA LOGO	Necessary	65.90 F	*65.90 FL
20	1		*TOYOTA STICKER	Necessary	30.00 F	*30.00 FL
21	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
22	1		*COMPANY STICKER	Necessary	10.00 FS	*10.00 FS
23	1		*SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,079.10</b>	<b>5,048.10</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$)</b>	0.00	1,044.53
<b>Total Parts (\$)</b>	<b>7,079.10</b>	<b>4,003.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO SPRAY TUFF COAT	New	150.00	60.00
7	TO REMOVE UPHOLSTERY	New	150.00	30.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>3,280.00</b>	<b>2,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >