

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22005756/AVCE2**Date:** 07/10/2022**REFERENCE**

Insured/Claimant:	PRIYA VERMA	Policy No:	7210012863	
Date of Loss:	08/06/2022	Nature of Claim:	OD	Claim No: 0583102351SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX8198E		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC23285
Reg. Date:	29/01/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF36M1058954
Colour:	White	Odometer:	14218 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$168,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,916.00	3,076.16	2,839.84	48.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,592.00	2,772.00	3,820.00	57.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,508.00	5,848.16	6,659.84	53.24
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	11,708.00	5,048.16	6,659.84	56.88
+ GST 7.00/7.00% (S\$)	819.56	353.37	466.19	56.88
Nett Amount (S\$)	12,527.56	5,401.53	7,126.03	56.88

INSPECTION

Date of Assignment:	17/06/2022	
Date Inspected:	15/06/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-LH	Distorted	3,127.00 FS	*2,501.60 FS
2	1		*REAR DOOR OUTER SEAL-LH	Necessary	151.00 FS	*120.40 FS
3	1		*REAR DOOR CATCH	Not Necessary	134.00 FS	*- FS
4	1		*REAR DOOR SEAL INNER-LH	Not Necessary	213.00 FS	*- FS
5	1		*REAR SILL PANEL SEAL-LH	Not Necessary	151.00 FS	*- FS
6	1		*REAR DOOR COVER-LH	Cut	270.00 FS	*216.00 FS
7	1		*REAR DOOR WINDOW REGULATOR-LH	Not Necessary	302.00 FS	*- FS
8	1		*REAR WHEEL ARCH COVER-LH	Missing	283.00 FS	*226.00 FS
9	2		*GROMMET	Necessary	7.00 FS	*4.96 FS
10	1		*REAR DOOR HANDLE,EXTERIOR-LH	Repair	222.00 FS	*- FS
11	1		*REAR DOOR HANDLE HOUSING-LH	Repair	31.00 FS	*- FS
12	1		*REAR WHEEL HOUSING LINER	Not Necessary	262.00 FS	*- FS
13	1		*REAR WHEEL SPOILER LH	Not Necessary	44.00 FS	*- FS
14	1		*SIDE MEMBER TRIM-LH	Not Necessary	189.00 FS	*- FS
15	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
16	1		*SUNDRIES	Necessary	350.00 FS	*7.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)

5,916.00

3,076.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	400.00	280.00
2	TO DISMANTLE AND RENEW LHS REAR DOOR.TO REPAIR LHS REAR FENDER,LHS SILL PANEL AND DOOR ENTRANCE.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS,REINSTALL ALL PARTS REMOVED	New	2,500.00	1,000.00
3	TO RESPRAY LHS REAR DOOR,LHS REAR FENDER,LHS SILL PANEL,DOOR HANDLE AND DOOR ENTRANCE	New	3,500.00	1,300.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,592.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >