

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005758/UCY3E2

Date: 27/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00138142102
Claimant Vehicle No: SMD3134C Insured Vehicle No: XD9829L
Date of Loss: 15/06/2022 Nature of Claim: TP Claim No: SNM22D204209/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD3134C
Make & Model: KIA CERATO, 1.6 EX (A) Engine No: G4FGJH702740
Reg. Date: 27/08/2018 (Man. Year: 2018) Chassis No: KNAF3416MK5012595
Colour: Grey Odometer: 51405 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Roadstone 7 mm Rear Left Side: Roadstone 7 mm
Front Right Side: Roadstone 7 mm Rear Right Side: Roadstone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,488.00	5,359.00	1,129.00	17.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,850.00	5,650.00	4,200.00	42.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,338.00	11,009.00	5,329.00	32.62
+ GST 7.00/7.00% (S\$)	1,143.66	770.63	373.03	32.62
Nett Amount (S\$)	17,481.66	11,779.63	5,702.03	32.62

INSPECTION

Date of Assignment: 23/06/2022
Date Inspected: 04/07/2022 Inspected At: Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)
330 Ubi Road 3
Singapore 408650
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2022)
Parts:	143	KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD3134C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*205/60 R16 TYRE ROAD STONE	Serviceable	128.00 FS	*- FS
2	1		*CERATO 16 RIM	Cut	1,250.00 FS	*1,250.00 FS
3	1		*RH PANEL-FENDER	Dented / Bent	593.00 FS	*593.00 FS
4	1		*RH INSULATOR-FENDER	Not Necessary	27.00 FS	*- FS
5	1		*RH MLDG ASSY-FR DR F	Necessary	37.00 FS	*37.00 FS
6	1		*RH W/STRIP ASSY-FR D	Not Necessary	64.00 FS	*- FS
7	1		*RH BLACK TAPE-FR DR	Necessary	13.00 FS	*13.00 FS
8	1		*RH PANEL ASSY-FR DOO	Badly Dented	1,377.00 FS	*1,377.00 FS
9	1		*RH UPR HINGE ASSY-FR	Not Necessary	30.00 FS	*- FS
10	1		*RH LWR HINGE ASSY-FR	Not Necessary	27.00 FS	*- FS
11	1		*RH MLDG ASSY-RR DR F	Necessary	44.00 FS	*44.00 FS
12	1		*RH W/STRIP ASSY-RR D	Not Necessary	60.00 FS	*- FS
13	1		*RH BLACK TAPE-RR DR	Necessary	13.00 FS	*13.00 FS
14	1		*RH BLACK TAPE-RR DR	Necessary	8.00 FS	*8.00 FS
15	1		*RH PANEL ASSY-RR DOO	Dented	1,445.00 FS	*1,445.00 FS
16	1		*RH UPR HINGE ASSY-RR	Not Necessary	33.00 FS	*- FS
17	1		*RH LWR HINGE ASSY-FR	Not Necessary	26.00 FS	*- FS
18	1		*RH MIRROR ASSY-OUTSI	Cracked	559.00 FS	*559.00 FS
19	1		*RH FILM-ANTI CHIPPG	Not fitted	27.00 FS	*- FS
20	1		*UPR COVER-RR BUMPER	Repair	651.00 FS	*- FS
21	10		*FASTENER-BUMPER	Necessary	20.00 FS	*20.00 FS
22	1		*RH UPR SIDE BRACKET	Not Necessary	31.00 FS	*- FS
23	1		*LH UPR SIDE BRACKET	Not Necessary	25.00 FS	*- FS
					Total Parts (\$\$)	6,488.00 5,359.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC / SCANNING	New	250.00	250.00
2	TO CHECK ALL LIGHTING / WIRING SYSTEM ON RHS ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO TRANSFER RHF & RHR DOOR COMPONENTS & MECHANISM PARTS	New	1,280.00	640.00
4	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS	New	300.00	100.00
5	TO REPLACE RHF FENDER, FENDER INSULATOR, RH SIDE MIRROR, RHF & RHD DOOR, DOOR HINGE, BLACK TAPE, DOOR MLDG, DOOR W/STRIP, UPR REAR BUMPER, CLIPS, ETC - TO REPAIR RHR FENDER. STRAIGHTEN, REFORM, ALIGN ON RHS ACCIDENT AFFECTED AREAS	New	3,840.00	1,600.00
6	SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS (HOOD, RH SIDE MIRROR, RHF FENDER, RHF & RHR DOOR, RHR FENDER, RR BUMPER)	New	3,850.00	2,750.00
7	WHEEL BALANCING (RHR TYRE & RIM)	New	50.00	50.00
8	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	180.00	180.00
Gross Labour Cost (\$\$)			9,850.00	5,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >