

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005761/TQY3Q2**Date:** 12/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00108982100		
Claimant Vehicle No :	SHD1687X	Insured Vehicle No :	GBK5624K		
Date of Loss:	16/06/2022	Nature of Claim:	TP	Claim No:	SNM22D204215/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1687X		
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Engine No:	D4FBHZ173214
Reg. Date:	04/10/2017 (Man. Year: 2017)	Chassis No:	TMAD281UVHJ141995
Colour:	Silver	Odometer:	392820 km
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,828.01	7,187.30	2,640.71	26.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	2,290.00	1,880.00	45.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,998.01	9,477.30	4,520.71	32.30
Approved Total (Overridden) (\$\$)		7,550.00		
(\$\$)	13,998.01	7,550.00	6,448.01	46.06
+ GST 7.00/7.00% (\$\$)	979.86	528.50	451.36	46.06
Nett Amount (\$\$)	14,977.87	8,078.50	6,899.37	46.06

INSPECTION

Date of Assignment:	20/06/2022		
Date Inspected:	17/06/2022	Inspected At:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Aug 2022)	
Parts:	N/A	HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD1687X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,292.30 FL	*2,292.30 FL
2	1		*TAILGATE LOWER GARNISH	Cracked	362.61 FL	*362.61 FL
3	1		*TAILGATE WEATHERSTRIP	Cut	276.98 FL	*276.98 FL
4	2		*TAILGATE HINGE	Repair	57.00 FL	*- FL
5	1		*TAILGATE LOCK	Bent	216.48 FL	*216.48 FL
6	2		*REAR LICENSE PLATE LAMP	Not Necessary	37.20 FL	*- FL
7	1		*REAR WINDSCREEN GLASS	Broken	397.90 FL	*397.90 FL
8	1		*REAR WINDSCREEN MOULDING	Necessary	64.10 FL	*64.10 FL
9	1		*END PANEL	Bent	853.85 FL	*853.85 FL
10	1		*END PANEL TOP GARNISH	Deformed	90.00 FL	*90.00 FL
11	1		*FLOORBOARD COMPARTMENT	Not Necessary	913.81 FL	*- FL
12	1		*EMBLEM I30	Necessary	27.80 FL	*27.80 FL
13	1		*EMBLEM CRDI	Necessary	29.40 FL	*29.40 FL
14	1		*EMBLEM HYUNDAI	Necessary	29.40 FL	*29.40 FL
15	2		*TAILGATE N/S & O/S REFLECTOR	Cracked	590.20 FL	*590.20 FL
16	2		*REAR N/S & O/S TAIL LAMP	Cracked	642.60 FL	*642.60 FL
17	1		*TAILGATE INNER TRIM	Cracked	431.12 FL	*431.12 FL
18	1		*LUGGAGE TRAY -CENTER RR	Deformed	299.48 FL	*299.48 FL
19	1		*REAR O/S FENDER	Repair	1,525.73 FL	*- FL
20	1		*REAR BUMPER	Cracked	811.11 FL	*811.11 FL
21	1		*REAR BUMPER SPONGE	Not Necessary	79.20 FL	*- FL
22	1		*REAR BUMPER REINFORCEMENT	Bent	815.64 FL	*815.64 FL
23	1		*REAR BUMPER REINFORCEMENT CENTRE	Not Necessary	79.20 FL	*- FL
24	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Deformed	104.40 FL	*104.40 FL
25	1		*REAR BUMPER N/S & O/S REFLECTOR	O/S Not Necessary / N/SCracked	215.00 FL	*107.50 FL
26	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
27	1		*SET REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
28	1		*SET TAILGATE STICKERS	Necessary	100.00 FS	*60.00 FS
29	1		*SET TAILGATE LOWER GARNISH CLIPS	Necessary	38.00 FS	*38.00 FS
30	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	38.00 FS	*- FS
31	1		*SET FLOORBOARD COMPARTMENT INSULATOR PADDINGS	Not Necessary	120.00 FS	*- FS
32	1		*REAR NUMBER PLATE	Cracked	50.00 FS	*45.00 FS
33	1		*SET SEALANT	Necessary	50.00 FS	*30.00 FS
34	1		*REAR N/S FENDER STICKER	Necessary	60.00 FS	*30.00 FS
35	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 12,076.51 8,875.87
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,248.50 1,688.57

Total Parts (\$\$) 9,828.01 7,187.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	50.00	50.00
2	TO DISMANTLE /REFIT REAR WINDSCREEN GLASS ONTO NEW TAILGATE	New	120.00	120.00
3	TO DISMANTLE AND REFIT THE INNER COMPONENTS OF WIPER ONTO NEW TAILGATE ,TEST WIPER MOTOR AND WATER ETC	New	120.00	60.00
4	TO DISMANTLE & REPLACE REVERSE SENSOR AND TEST SYSTEM	New	80.00	30.00
5	TO LABOUR CHARGE FOR DISMANTLE AND RENEWAL OF THE ACCIDENT DAMAGED PARTS .TO HEAT /WELD & CUT END PANEL AND FLOORBOARD COMPARTMENT INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR RESHAPE OF THE N/S ROOFTOP PANEL ETC	New	2,200.00	1,000.00
6	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE ,TAILGATE LOWER GARNISH ,END PANEL ,FLOORBOARD COMPARTMENT ,REAR N/S FENDER ,TOP N/S ROOFTOP PANEL	New	1,400.00	1,000.00
7	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	30.00
Gross Labour Cost (\$\$)			4,170.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >