

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005763/RQY3Q2**Date:** 07/09/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00059882200

Claimant Vehicle No : SG6156H**Insured Vehicle No :** SGT7769G

Date of Loss: 27/05/2022

Nature of Claim: TP

Claim No: SNM22D203804/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SG6156H**

Make & Model: MAN A95, 10.5 D (A)

Engine No: 50352380945233

Reg. Date: 13/02/2020 (Man. Year: 2018)

Chassis No: WMAA95ZZ5KF009191

Colour: Green

Odometer: 167081 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	884.00	884.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,188.00	1,188.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,072.00	2,072.00	0.00	0.00
+ GST 7.00/7.00% (\$\$)	145.04	145.04	0.00	0.00
Nett Amount (\$\$)	2,217.04	2,217.04	0.00	0.00

INSPECTION

Date of Assignment: 05/09/2022

Date Inspected: 17/06/2022 Inspected At:

Sbs Transit Pte Ltd (ulu Pandan) (HQ)
Ulu Pandan WS, 1 Business Park Drive,
Singapore 608506

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Sep 2022)	
Parts:	N/A	MAN A95 10.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG6156H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NS NO 3 BODY PANEL	Bent	232.00 F	*232.00 F
2	1		*NS NO 4 BODY PANEL	Bent	200.00 F	*200.00 F
3	1		*NS NO 5 BODY PANEL	Bent	200.00 F	*200.00 F
4	2		*WHEEL ARCH	Scratched	200.00 F	*200.00 F
5	4		*BOSTICK SEALANT	Necessary	52.00 F	*52.00 F
Total Parts (S\$)						884.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	1,000.00	1,000.00
2	SPRAY PAINT & PUTTY	New	188.00	188.00
3	STICKER LIVERY (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			1,188.00	1,188.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >