

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22005764/AGVY3E2**Date:** 04/01/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001836496

Claimant Vehicle No : SNC3768S**Insured Vehicle No :** SMP5279S

Date of Loss: 16/06/2022

Nature of Claim: TP Claim No: 276792

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNC3768S**

Make & Model: HONDA VEZEL, 1.5 X HYBRID CVT (A)

Engine No: LEC1012020

Reg. Date: 15/10/2021 (Man. Year: 2021)

Chassis No: RV51009674

Colour: Black

Odometer: 49402 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,835.50	6,182.40	7,653.10	55.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,230.00	2,820.00	1,410.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,065.50	9,002.40	9,063.10	50.17
Approved Total (Overridden) (S\$)		7,200.00		
Nett Amount (S\$)	18,065.50	7,200.00	10,865.50	60.15

INSPECTION

Date of Assignment: 17/06/2022

Date Inspected: 16/06/2022 Inspected At:

ADVANCE AUTO GARAGE (23 KAKI BUKIT) (HQ)
25 KAKI BUKIT AVE 4 #04-01 VICOM KAKI BUKIT
Singapore 415933

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC3768S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Distorted	865.50 F	*865.50 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	1		*REAR BUMPER SIDE HOLDER	N/S Damaged	98.60 F	*49.30 FL
6	1		*REAR BUMPER REFLECTOR	N/S Cracked	302.20 F	*151.10 FL
7	1		*REAR BUMPER LOWER	Deformed	325.80 F	*325.80 FL
8	1		*REAR BUMPER LOWER GARNISH (SILVER)	Deformed	195.90 F	*195.90 FL
9	1		*REAR BUMPER UNDERCOVER LH	Deformed	145.90 F	*145.90 FL
10	1		*REAR END PANEL	Distorted	595.90 F	*595.90 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	272.20 F	*272.20 FL
12	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
13	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
14	1		*REVERSE SENSOR (4PCS)	Damaged (2Pcs Only)	656.00 F	*328.00 FL
15	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	453.70 F	*- FL
16	1		*TAILLAMP LH	Not Necessary	595.40 F	-
17	1		*TAILGATE	Distorted	1,361.20 F	*1,361.20 FL
18	1		*TAILGATE LOCK	Damaged	280.40 F	*280.40 FL
19	1		*TAILGATE WEATHERSTRIPE	Cut	168.40 F	*168.40 FL
20	1		*TAILGATE OUTER GARNISH	Deformed	468.70 F	*468.70 FL
21	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
22	1		*TAILGATE INNER TRIM BOARD	Cracked	298.40 F	*298.40 FL
23	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
24	2		*TAILGATE REFLECTOR	Not Necessary	1,972.80 F	*- FL
25	1		*TAILGATE GLASS MOULDING	Necessary	278.50 F	*278.50 FL
26	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
27	1		*HONDA LOGO	Necessary	65.40 F	*65.40 FL
28	1		*VEZEL WORDING	Necessary	68.20 F	*68.20 FL
29	1		*HYBRID EMBLEM	Necessary	59.40 F	*59.40 FL
30	1		*REAR LH FENDER	Repair	1,280.40 F	*- FL
31	1		*REAR LH FENDER OUTER ARC GARNISH	Deformed	195.50 F	*195.50 FL
32	1		*REAR LH FENDER OUTER ARC GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
33	1		*REAR LH FENDER INNER TRIM BOARD	Deformed	399.20 F	*399.20 FL
34	1		*REAR LH FENDER INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
35	1		*REAR LH FENDER INNER SHIELD	Torn	189.40 F	*189.40 FL
36	1		*REAR LH FENDER INNER SHIELD CLIPS	Necessary	20.00 FS	*20.00 FS
37	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	557.40 F	*- FL
38	1		*SPARE TYRE SIDE PANEL LH	Repair	394.20 F	*- FL
39	1		*UTILITY TRAY	Cracked	328.40 F	*328.40 FL
40	1		*CHARCOAL CANISTER	Not Necessary	340.20 F	*- FL
41	1		*CHARCOAL CANISTER BRACKET	Bent	65.90 F	*65.90 FL

Report was unsubmitted during this print-out.

1/4/23, 9:57 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*REAR END PANEL ANTENNA SENSOR	Cracked	196.40 F	*196.40 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	13,835.50
					7,653.00	
					- List Item Discount on L Items 0.00/20.00% (\$)	0.00
					1,470.60	
					Total Parts (\$)	13,835.50
					6,182.40	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,200.00
2	SPRAY PAINTING	New	1,400.00	1,100.00
3	WIRING	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE VIDEO RECORDER	New	100.00	50.00
7	TO SPRAY TUFF COAT	New	150.00	80.00
8	TO REMOVE UPHOLSTERY	New	150.00	60.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
Gross Labour Cost (\$\$)			4,230.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >