

SNC 3768S.

The cut on the tailcap is probably due to the vibration, and abrasion between the LH tailcap and LH Tailgate Latch when the impact ~~occurred~~ caused the tailgate to shift laterally.

I hope that the above clarifies matter.