J&M CONSULTANCY PTE LTD

11 Changi South Lane #02-08 ONN WAH BUILDING Singapore 486154 Company Reg No: 202125502E Tel: 6214-0474 Fax: 6384-5205

Xino Chen

VEHICLE INSPECTION REPORT

To: A-TEC AUTOCITY PTE LTD

Date

24 March 2022

C/o: A-Tec Automotive Pte Ltd

Our ref

: ATEC/03/0009/JM

8 Kaki Bukit Avenue 4

#04-20 Premier @ Kaki Bukit, Singapore 415875

Accident Date : 26 January 2022

Inspection Date: 26 January 2022

Repairer Name : A-Tec Automotive Pte Ltd

8 Kaki Bukit Avenue 4

#04-20 Premier @ Kaki Bukit, Singapore 415875

PARTICULARS OF VEHICLE

Registration No

: GBL 5416 P

Year / Capacity: 2021/ 1598 cc

Type of Survey: Third party

Make / Model

: Nissan / NV200

Colour

: Silver

Chassis No

: JN1YAAN20Z0001883

Mileage

: 6846 Km

Engine No

: HR16185394D

CONDITION OF TYRES

		Make	Size	Thread Balance
Front Nearside	:	Toyo	165/80 R14	80%
Front Offside	:	Toyo	165/80 R14	80%
Rear Nearside	:	Toyo	165/80 R14	80%
Rear Offside	;	Toyo	165/80 R14	80%

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front and rear bumper portion.

(Details refer to the photographs attached)

Enclosed number of photographs:

93

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

Vehicle Registration No: GBL 5416 P

Our Ref No: ATEC/03/0009/JM

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

Under normal circumstances, the repair period would be about 25 (Twenty Five) working days.

Qty	Description	Condition		Repairer's Estimate		Revised Amount
	SPARE PARTS - LIST ITEMS (Front)					65
1	Front bumper assy	Warped	\$	1,500.00	\$	1.500.00
1	Front bumper RH	Warped	\$	620.00	\$	620.00 3
1	Front bumper LH	Warped	\$	620.00	\$	820.00
1	Front bumper brackets (1 set)	Cracked/Necessary	\$	488.00	\$	488.00 X
1	Front bumper retainers (1 set)	Cracked/Necessary	\$	478.00	\$	478.00
1	Front bumper absorber foam	Cracked	\$	468.00	\$	468,00
1	Front bumper grille lower	Warped	\$	580.00	\$	580,00
1	Front grille assy Front grille emblem Front headlamp LH 36/6 20	Warped	\$	528.00	\$	528.00
1	Front grille emblem	Reuse	\$	150.00	\$	105000
1	Front headlamp LH 36/6 20	Cracked	\$	1,650.00		1,000.00
1	Front headlamp RH	Cracked	\$	1,650.00	\$	1,650.00
1	Front bonnet assy	Crushed/Warped	\$	1,380.00	\$	1,380.00
		Total	\$	10,112.00	\$	9,962.00
		Less 30%	\$	3,033.60	\$	2,988.60
			\$	7,078.40	\$	6,973.40
	SPECIAL NETT ITEMS (Front)					
1	Front bumper clip (1 set)	Necessary	\$	100.00	\$	100,00 30
1	Front bumper grille lower clips (1 set)	Necessary	\$	100.00	\$	100.00 40
1	Front grille clips (1 set)	Necessary	\$	100.00	\$	100.00 2
1	Front vehicle plate (1 set)	Warped _	\$	120.00	\$	-120.00 6
	150		\$	420.00	\$	420.00
	Total parts - Front		\$	7,498.40	\$	7,393.40

Vehicle Registration No: GBL 5416 P

Our Ref No: ATEC/03/0009/JM

Qty	Description	Condition	epairer's Estimate	Revised Amount	Contract Con
	SPARE PARTS - LIST ITEMS (Rear)				
1	Rear bumper assy	Dented/Warped	\$ 1,200.00	\$ (1,200.00
1	Rear bumper impact absorber	Dented	\$ 468.00	\$	468.00
1	Rear bumper retainer (1 set)	Necessary	\$ 478.00	\$	478.00
1	Rear tailgate assy	Dented/Warped	\$ 1,500.00	\$	1,500.00
1	Rear taillamp RH	Cracked	\$ 1,150.00	\$	1,150.00
1	Rear taillamp LH	Cracked	\$ 1,150.00	\$	1,150.00
1	Rear '3rd' brake lamp M M	Cracked	\$ 685.00	\$	685.00
1	Rear tailgate lock	Malfunction	\$ 523.00	\$	523.00
1	Rear tailgate lock handle	Malfunction	\$ 133.00	\$	133.00 X
1	Rear tailgate inner remote lock New	Malfunction	\$ 638.00	\$	638.00 ×
1	Rear tailgate weatherstrip ##~	Torn/Necessary	\$ 328.00	\$	328.00 Y
1	Rear tailgate lock catch	Reuse	\$ 120.00	\$	- X
1	Rear tailgate lock catch cover NN	Cracked	\$ 365.00	\$	365.00
1	Rear tailgate dampers (1 set)	Bent/Necessary	\$ 686.00	\$	686.00 X
1	Rear tailgate wiper motor	Malfunction	\$ 585.00	\$	585.00
1	Rear tailgate windscreen	Cracked	\$ 750.00	\$	750.00
1	Rear tailgate mirror HM	Bent	\$ 520.00	\$	520.00
1	Rear end panel for 4091	Dented/Warped	\$ 780.00	\$	780.00
			\$ 12,059.00	\$	11,939.00
	3 681.	Less 30%	\$ 3,617.70	\$	3,581.70
			\$ 8,441.30	\$	8,357.30
	SPECIAL NETT ITEMS (Rear)				
1	Rear bumper clips (1 set)	Necessary	\$ 100.00	\$	100.00 3
1	Rear "Nissan" logo emblem	Necessary	\$ 150.00	\$	150.00 53
1	Rear wiper blade	E Bent/Necessary	\$ 120.00	\$	120.00 5
1	Rear "NV200" emblem	Necessary	\$ 180.00	\$	180.00 7
1	"70 Km/h" Sticker	Necessary	\$ 25.00	\$	25.00 15
1	Rear windscreen glass sealant	Necessary	\$ 120.00	\$	120.00-60
	y		\$ 695.00	\$	695.00

Vehicle Registration No: GBL 5416 P

Our Ref No: ATEC/03/0009/JM

500	Total cost of all parts c/f		\$ 16,634.70		16,445.70	
S/No	Description		Repairer's Estimate		Revised Amount	
					Angaro's to read	
1	To cut, weld, straighten affected areas and replace damaged parts.	\$	4,400.00	\$	4,000.00 12	
2	To putty and spray painting the affected areas. Job Allowance.	\$	4,400.00	\$	4,000.00 /	
3	To check front & rear lighting and wiring.	\$	350.00	\$	300,00	
4	To remove and install front & rear inner garnish and trim to facilitate the repair.	\$	320.00	\$	300,00 8	
5	To apply anti rust proofing to the affected areas.	\$	350.00	\$	300.00 80	
6	To remove and install front & rear bumper assy.	\$	520.00	\$	500.00 ×	
7	To remove and install front & rear tailgate emblems & stickers	\$	280.00	\$	260.00 ×	
8	To remove and install rear tailgate assy and components.	\$	280.00	\$	260.00 80	
9	To remove and install front bumper assy.	\$	280.00	\$	260.00	
10	To remove and install front bumper grille assy.	\$	280.00	\$	260.00 ×	
11	To remove and install rear windscreen.	\$	280.00	\$	260.00 2	
12	To remove and install rear wiper components.	\$	280.00	\$	260.00	
13	To remove and install front headlamps.	\$	280.00	\$	260.00	
14	To remove and install rear taillamps.	\$	280.00	\$	260.00	
15	To remove and install front & rear lock mechanism	\$	520.00	\$	500.00	
16	To check central door locking system	\$	100.00	\$	80.00	
17	To conduct chassis alignment	\$	350.00	\$	300.00 ×	
	Grand Total:	\$	30,184.70	\$	28,805.70	

Vehicle Registration No: GBL 5416 P

Our Ref No: ATEC/03/0009/JM

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 23,000

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notiffed the company within (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

tolal: 10353.10.

Hs: 8250

J&M Consultancy Pte Ltd

UEN NO : 202125502F

Joel Liew Jian Xiang

Automotive Appraiser

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Si l'ature: