

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/HLA22005765/ECY3M4**Date:** 22/12/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP317325
<b>Claimant Vehicle No :</b>	SLE7373J	<b>Insured Vehicle No :</b>	SKW7741Y
Date of Loss:	12/06/2022	Nature of Claim:	TP
		Claim No:	MPC03493

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLE7373J</b>		
Make & Model:	SUBARU XV, 2.0 I-S EYESIGHT AWD CVT (A)	Engine No:	FB20CG88046
Reg. Date:	19/11/2020 (Man. Year: 2019)	Chassis No:	JF1GT7KL5LG094351
Colour:	White	Odometer:	8042 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,380.24	3,393.20	987.04	22.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,915.00	3,305.00	1,610.00	32.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,295.24</b>	<b>6,698.20</b>	<b>2,597.04</b>	<b>27.94</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>650.67</b>	<b>468.87</b>	<b>181.80</b>	<b>27.94</b>
<b>Nett Amount (S\$)</b>	<b>9,945.91</b>	<b>7,167.07</b>	<b>2,778.84</b>	<b>27.94</b>

INSPECTION

Date of Assignment:	16/06/2022	
Date Inspected:	20/06/2022	Inspected At: Motor Image Enterprises Pte Ltd (Leng Kee) 25 Leng Kee Road Singapore 159097
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2022)
<b>Parts:</b>	M1-SUV	SUBARU XV 2.0 I-S EYESIGHT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLE7373J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER PUNCHING RXV	Dented	414.40 FN	*414.40 FN
2	1		*BRKT SD R XV RH	Not Necessary	12.40 FN	*- FN
3	1		*BRKT SD R XV LH	Not Necessary	12.40 FN	*- FN
4	1		*BRKT LWR R X2	Broken	26.00 FN	*26.00 FN
5	1		*BEAM COMPL R EU	Bent	208.60 FN	*208.60 FN
6	1		*COVER SD LWR XV RH	Not Necessary	21.50 FN	*- FN
7	1		*COVER SD LWR XV LH	Not Necessary	21.50 FN	*- FN
8	1		*COVER HOOK R XV	Not Necessary	6.70 FN	*- FN
9	1		*PANEL COMPL R GAT	Dented	940.00 FN	*940.00 FN
10	1		*GLASS ASSY R G	Necessary	1,091.50 FN	*1,091.50 FN
11	1		*STRIKER R/G	Not Necessary	22.20 FN	*- FN
12	1		*WSTR DR R G	Not Necessary	111.00 FN	*- FN
13	1		*DAM RUBBER	Necessary	18.50 FN	*18.50 FN
14	1		*LENS & BODY COMPLLH	Not Necessary	199.80 FN	*- FN
15	1		*LENS & BODY COMPLLH	Not Necessary	370.00 FN	*- FN
16	1		*LENS & BODY COMPLRRH	Broken	133.20 FN	*133.20 FN
17	1		*LENS & BODY COMPLRLH	Not Necessary	66.60 FN	*- FN
18	1		*GARNISH SC	Not Necessary	178.70 FN	*- FN
19	1		*TRIM PNL AY SKIRTT	Not Necessary	111.00 FN	*- FN
20	1		*LENS & BODY COMPLRH	Broken	370.00 FN	*370.00 FN
21	1		*SNR SENS ASSY (SUPP)	Broken	233.10 FN	*233.10 FN
22	1		*SNR CAP ASSY (SUPP)	Broken	37.00 FN	*37.00 FN
23	1		*ORNAMENT ASSY F SIX	Necessary	70.30 FN	*70.30 FN
24	1		*LETTER MK R	Necessary	92.50 FN	*92.50 FN
25	1		*LETTER MK R XV	Necessary	37.00 FN	*37.00 FN
26	1		*EYE SIGHT EMBLEM (TCS) (SUPP)	Necessary	44.40 FN	*44.40 FN
27	1		*REVERSE SENSOR - 4 EYES	Broken	400.00 FS	*400.00 FS
28	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$)</b>	<b>5,350.30</b>	<b>4,136.50</b>
<b>- Nett Item Discount on N Items 20.00/20.00% (\$)</b>	970.06	743.30
<b>Total Parts (\$)</b>	<b>4,380.24</b>	<b>3,393.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPAIR/REPLACE REAR BUMPER, PANEL & TAILGATE	New	1,680.00	1,120.00
2	RESPRAY REAR BUMPER, PANEL & TAILGATE	New	1,260.00	840.00
3	REMOVE & REFIX EXHAUST	New	150.00	0.00
4	TRANSFER TAILGATE MECHANISM	New	150.00	150.00
5	WHEEL ALIGNMENT	New	200.00	0.00
6	FAULT DIAGNOSTIC	New	280.00	0.00
7	REMOVE & INSTALL REAR WINDSCREEN	New	300.00	300.00
8	CONDUCT REAR LIGHTING TEST	New	50.00	50.00
9	SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	New	145.00	145.00
10	REPAIR REAR END PANEL (SUPP)	New	280.00	280.00
11	RESPRAY REAR BUMPER BEAM & END PANEL (SUPP)	New	420.00	420.00
<b>Gross Labour Cost (S\$)</b>			<b>4,915.00</b>	<b>3,305.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >