

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS22005768/AQY3E2

Date: 28/07/2022

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000571179
Claimant Vehicle No : SMU906Y **Insured Vehicle No :** GX6699K
Date of Loss: 12/06/2022 Nature of Claim: TP Claim No: 202222005199KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU906Y**
Make & Model: BMW 318i, 2.0 L (A) Engine No: F3421448B38B15A
Reg. Date: 27/10/2016 (Man. Year: 2016) Chassis No: WBA8E36030NU32174
Colour: Red Odometer: 57581 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,218.00	3,799.80	3,418.20	47.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	970.00	1,810.00	65.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,998.00	4,769.80	5,228.20	52.29
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	9,998.00	3,800.00	6,198.00	61.99

INSPECTION

Date of Assignment: 17/06/2022
Date Inspected: 17/06/2022 Inspected At: #02-13, 8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit
Estimated Period of Repair: 4.0 days Repairer: Auto Mega Mall Pte Ltd (HQ)

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2022)
Parts:	143	BMW 318I 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU906Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,699.00 FL	*1,392.00 FL
2	1		*FRONT BUMPER BRACKET RH	Damaged	156.00 FL	*95.00 FL
3	1		*FRONT BUMPER BRACKET LH	Not Necessary	156.00 FL	*- FL
4	1		*FRONT RH FENDER	Repair	1,056.00 FL	*- FL
5	1		*FRONT HEADLAMP	Cracked	2,180.00 FL	*2,180.00 FL
6	1		*FRONT RH FOG LAMP COVER	Cracked	355.00 FL	*125.00 FL
7	1		*FRONT RH FOG LAMP	Cracked	651.00 FL	*285.00 FL
8	1		*FRONT REINFORCEMENT SPONGE	Cracked	365.00 FL	*145.00 FL
9	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	265.00 FL	*- FL
10	1		*FRONT RIGHT WHEEL ARC COWLING	Not Necessary	278.00 FL	*- FL
11	1		*FRONT REINFORCEMENT BAR	Not Necessary	859.00 FL	*- FL
					Sub Total (\$\$)	8,020.00 4,222.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	802.00 422.20
					Total Parts (\$\$)	7,218.00 3,799.80

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FIX & DISMANTLE AND REMOVE DAMAGED FRONT RH PORTIONS; AFFECTED DAMAGED PORTION	New	1,000.00	400.00
2	TO APPLY ANTI RUST COAT AND AFFECTED AREAS (NPA)	New	0.00	0.00
3	TO CHECK WIRING	New	180.00	30.00
4	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT (NPA)	New	0.00	0.00
5	SPRAY PAINTING FOR FRONT RH PORTIONS AFFECTED PARTS	New	1,000.00	500.00
6	REFOCUSING OF THE FRONT HEADLAMP	New	180.00	0.00
7	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE	New	120.00	0.00
8	3D WHEEL ALIGNMENT	New	120.00	0.00
9	TO APPLY WATERPROOFING SEALER ON END PANELS	New	180.00	40.00
Gross Labour Cost (\$\$)			2,780.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >