



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 5555P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (WCP)	BUCKLED	340.00	340.00
1	FRONT BUMPER SIDE RETAINER LH (WCP)	DISTORTED	10.00	10.00
1	FRONT BUMPER LOWER SKIRT (WCP)	CUT	140.00	140.00
6	FRONT BUMPER CLIP @\$2.00 (WCP)	NECESSARY	12.00	12.00
1	FRONT LH FENDER (WCP)	BENT	180.00	180.00
1	FRONT LH FENDER WHEEL ARP GARNISH (WCP)	CUT	55.00	55.00
1	FRONT LH HEADLAMP (WCP)	MTG CRACKED	920.00	920.00
	COST PLUS 10%		165.70	165.70
			1,822.70	1,822.70
<b><u>LABOUR</u></b>				
	TO REMOVE AND REFIX FRT BUMPER, FRT LH FENDER, HEADLAMP; KNOCK AND REPAIR FRT BUMPER REINFORCEMENT AND RE-ALIGN TO SAME.		450.00	360.00
	TO PUTTY AND RESPRAY ON FRT BUMPER, FRT LH FENDER.		500.00	400.00
			950.00	760.00
<b>GRAND TOTAL</b>			<b>2,772.70</b>	<b>2,582.70</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,582.70</b>

Report Ref No. CS/SMO22005770/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.