

**FINAL COST OF REPAIR**  
(To be completed for only one type of item)

To:  <div style="text-align: center; color: red;">             HD TPT CENTRE WEST, TPTHUBWEST              PLC NODE              HD TPT RESOURCE, TPTHUBWEST              RESOURCE SUP IC, TPTHUBWEST           </div> <div style="text-align: center;">Unit</div>		From:  <div style="text-align: center; color: red;">MAO/PLC CSW</div> <div style="text-align: center;">Base/LEO Area Office</div>	
Description of Item:		MAN 16.284 LAERC	
Part/Reg No: MID20919		Original Value: -	SAF 1222: BB72/PLC/D/XX/XX
Quantity: 01		CE/Non CE: -	SAF 1204/SAF1351:
Description of Damages and Costs of Repairs:		Date:	
		Accident Job No:	
		Date:	
S/N	<u>Incident Repair</u>		<u>Man-hours</u>
1	LEFT SIDE MIRROR ARM BENT		3.00
2	LEFT SIDE MIRROR BROKEN		
3	LEFT SIDE BLIND SPOT MIRROR CRACK		
4	LEFT SIDE CURB MIRROR BROKEN		
S/N	<u>Materials Cost</u>	<u>Unit Price</u>	<u>Qty</u> <u>COST</u>
1	ARM,REARVIEW MIRROR:LEFT SIDE	\$84.00	1      \$84.00
2	MIRROR HEAD,VEH:RECTANGULAR W/ROUND ENDS	\$38.23	1      \$38.23
3	MIRROR HEAD,VEHICULAR:GLASS,RECT,OUTSIDE	\$89.27	1      \$89.27
4	CURB,MIRROR:	\$86.01	1      \$86.01
<b>Base/LEO Area Office's Assessment of Damages</b>			
Labour Charges @		\$79.81	per hour X 3.00 hrs      hrs      =      \$239.43
Total Cost of Parts / Materials Used			=      \$297.51
Sub-contractor			=      -
Assessment Fee			=      -
Towing Service			=      -
Total			<b>\$536.94</b>
Estimated Time for Repair:			3 Hrs

\*Delete whichever is not applicable  
FINAL COST OF REPAIR

