

**ESTIMATED COST OF REPAIR**

(To be completed for only one type of item)

To:  <div style="text-align: center;">KРАНJI TPT NODE Unit</div>		From:  <div style="text-align: center;">SHI ZHANGSONG Base/LEO Area Office</div>		Ref: BB75/(9AMB)/92FMD/22/009  <div style="text-align: center;">Digitally signed by SHI ZHANGSONG Date: 2022.06.20 9:49:38 +08'00'</div>	
Description of Item: TRK,CARGO:MAN 5TON HARD ROOF MTD W/BCS		SAF 1222:	NIL		
Part/Reg No: MID22002	Original Value: \$204,053	Date:	NIL		
Quantity: 01	CE/Non CE: Non CE	SAF 1204/SAF 1351:	8202764756		
Description of Damages and Costs of Repairs:		Date:	02.06.2022		
		Workshop Job No:	8202764756		
		Date:	02.06.2022		
<u>MATERIAL COST</u>					
DESCRIPTION		Qty	Unit Price	Total Price	
<u>LABOUR COST</u>		ManHour	0.5	Rate	\$32.96
CSW IN-INSPECTION					\$16.48
<b>Base/LEO Area Office's Assessment of Damages</b>					
Labour Charges @ \$79.48 per hour x 0		hrs =	\$-	p	
Total Cost of Parts / Materials Used		=	\$-		
Sub-contractor		=	\$0.00		
Assessment Fee		=	\$0.00		
Towing Service		=	\$0.00		
7% GST					
Grand Total			\$-		
Estimated Time for Repair:					

\*Delete whichever is not applicable

ESTIMATED COST OF REPAIR