

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122005778/EVY3M4**Date:** 19/09/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SLB7019Z **Insured Vehicle No :** GBK8880S

Date of Loss: 02/06/2022 Nature of Claim: TP Claim No: CDMCG22001107

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB7019Z**

Make & Model: HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) Engine No: L15B4033762

Reg. Date: 19/04/2016 (Man. Year: 2016) Chassis No: RU11113756

Colour: Blue Odometer: 96324 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16 Rear Tyre Size: 205/65 R16

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,793.41	347.78	4,445.63	92.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,080.00	700.00	4,380.00	86.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,873.41	1,047.78	8,825.63	89.39
+ GST 7.00/7.00% (S\$)	691.14	73.34	617.80	89.39
Nett Amount (S\$)	10,564.55	1,121.12	9,443.43	89.39

INSPECTION

Date of Assignment: 17/06/2022

Date Inspected: 21/06/2022 Inspected At: Vantage Automotive Limited (Alexandra)
305 Alexandra Road #02-01, Vantage Automotive Centre
Singapore 159942

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$302.76 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Sep 2022)

Parts: 144 HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB7019Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	805.95 FS	*- FS
2	2		*BONNET HINGE	Not Necessary	82.62 FS	*- FS
3	1		*BONNET LOCK	Not Necessary	88.65 FS	*- FS
4	1		*BONNET STAND CLIP	Not Necessary	8.64 FS	*- FS
5	1		*BONNET STAND GROMMET	Not Necessary	5.76 FS	*- FS
6	1		*BONNET HOLE PLUG	Not Necessary	3.15 FS	*- FS
7	2		*BONNET RUBBER FRONT	Not Necessary	42.12 FS	*- FS
8	2		*BONNET RUBBER CORNER	Not Necessary	42.48 FS	*- FS
9	2		*BONNET RUBBER SIDE	Not Necessary	67.50 FS	*- FS
10	1		*FRONT BUMPER	Repair	413.55 FS	*- FS
11	1		*FRONT BUMPER TOWING COVER	Not Necessary	17.46 FS	*- FS
12	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	69.75 FS	*- FS
13	1		*FRONT BUMPER LOWER LID	Not Necessary	189.36 FS	*- FS
14	1		*FRONT BUMPER LOWER RUBBER	Not Necessary	76.41 FS	*- FS
15	2		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	70.92 FS	*- FS
16	2		*FRONT BUMPER SIDE RETAINER	* Check	31.68 FS	*- FS
17	1		*REINFORCEMENT	Not Necessary	289.26 FS	*- FS
18	2		*REINFORCEMENT RUBBER	Not Necessary	43.56 FS	*- FS
19	2		*AIR GUIDE	Not Necessary	65.88 FS	*- FS
20	1		*FRONT GRILLE BASE	* Check	271.08 FS	*- FS
21	1		*FRONT GRILLE OUTER GARNISH	Cut	256.86 FS	*256.86 FS
22	2		*FRONT GRILLE CHROME	Cut	70.92 FS	*70.92 FS
23	1		*FRONT GRILLE CENTER BRACKET	Not Necessary	28.89 FS	*- FS
24	2		*FRONT GRILLE SIDE BRACKET	Not Necessary	34.92 FS	*- FS
25	1		*FRONT GRILLE TOP COVER	Not Necessary	76.86 FS	*- FS
26	1		*HEADLAMP LEFT	Not Necessary	1,539.18 FS	*- FS
27	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,793.41** **347.78**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE BONNET, LOCK, GRILLE, FRONT BUMPER, LOWER GRILLE, LOWER LID, REINFORCEMENT, LEFT HEADLAMP ETC. REPAIR PANELS	New	2,400.00	300.00
2	TO RESPRAY FRONT BONNET, FRONT BUMPER, GRILLE ETC	New	1,800.00	300.00
3	TO CARRY OUT BODY CAVITY PRESERVATION	New	60.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEM OF THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	150.00	50.00
5	TO CONDUCT REPROGRAMMING & RESETTNG OF ECU SYSTEM INCLUDING CLEARING OF FAULT CODES	New	600.00	0.00
6	TO SUPPLY & INSTALL FRONT LICENSE PLATE WITH CASING (NETT)	New	70.00	50.00
Gross Labour Cost (\$\$)			5,080.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >