

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005782/ANY3Q2**Date:** 28/09/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00136222104

**Claimant Vehicle
No :** SJP255D**Insured Vehicle
No :** GBH8480D

Date of Loss: 16/06/2022

Nature of Claim: TP

Claim
No: SNM22D204216/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJP255D**

Make & Model: HYUNDAI HD AVANTE, 1.6 (A)

Engine No: G4FC9U614097

Reg. Date: 10/03/2009 (Man. Year: 2009)

Chassis No: KMH DU41BR9U706148

Colour: Grey

Odometer: 200782 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,309.04	5,190.88	4,118.16	44.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,920.00	2,310.00	2,610.00	53.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,229.04	7,500.88	6,728.16	47.28
Approved Total (Overridden) (\$\$)		6,000.00		
Nett Amount (\$\$)	14,229.04	6,000.00	8,229.04	57.83

INSPECTION

Date of Assignment: 17/06/2022

Date Inspected: 17/06/2022 Inspected At:

HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2022)
Parts:	143	HYUNDAI HD AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP255D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	489.00 FL	*489.00 FL
2	2		*REAR BUMPER RETAINER	Necessary	99.60 FL	*99.60 FL
3	5		*REAR BUMPER BRACKET	Not Necessary	99.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Cracked	349.70 FL	*349.70 FL
5	2		*REAR BUMPER REINFORCEMENT BRACKET	Dented	174.40 FL	*174.40 FL
6	1		*REAR BUMPER SPONGE	Cracked	194.30 FL	*194.30 FL
7	1		*BOOTLID	Dented	985.90 FL	*985.90 FL
8	1		*BOOTLID OUTER MOULDING	Cracked	247.80 FL	*247.80 FL
9	1		*BOOTLID LOGO	Necessary	57.40 FL	*57.40 FL
10	1		*BOOTLID EMBLEM AVANTE	Necessary	47.40 FL	*47.40 FL
11	1		*BOOTLID EMBLEM S	Necessary	32.60 FL	*32.60 FL
12	2		*BOOTLID NIMBER PLATE LAMP	Not Necessary	98.40 FL	*- FL
13	2		*BOOTLID STOPPER	Not Necessary	36.20 FL	*- FL
14	1		*BOOTLID INSULATOR	Not Necessary	197.90 FL	*- FL
15	2		*BOOTLID HINGE	Bent	241.60 FL	*241.60 FL
16	1		*BOOTLID TOP LOCK	Damaged	152.90 FL	*152.90 FL
17	1		*BOOTLID LOWER LOCK	Not Necessary	42.70 FL	*- FL
18	1		*BOOTLID WEATHERSTRIP	Cut	159.50 FL	*159.50 FL
19	2		*TAILLAMP	Cracked	679.60 FL	*679.60 FL
20	1		*TAILLAMP PANEL	N/S Dented	381.60 FL	*190.80 FL
21	1		*REAR WINDSCREEN MOULDING	Not Necessary	163.50 FL	*- FL
22	1		*REAR FENDER LH	Not Necessary	1,653.40 FL	*- FL
23	2		*REAR FENDER COWLING	Not Necessary	197.40 FL	*- FL
24	1		*REAR FENDER QUARTER GLASS LH	Not Necessary	297.90 FL	*- FL
25	1		*REAR FENDER INNER TRIM	N/S Deformed	597.20 FL	*298.60 FL
26	1		*REAR END PANEL	Dented	586.90 FL	*586.90 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	142.60 FL	*142.60 FL
28	1		*REAR FLOOR PANEL TOP BOARD	Deformed	367.40 FL	*258.00 FL
29	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
30	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
31	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
32	1		*BOOTLID SPOILER	Damaged	750.00 FS	*480.00 FS
33	1		*SET BOOTLID OUTER HANDLE GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
34	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*30.00 FS
35	2		*TAIL LAMP PANEL SEALANT	Necessary	160.00 FS	*30.00 FS
36	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
37	1		*REAR WINDSCREEN INNER SHIELD	Not Necessary	80.00 FS	*- FS
38	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	50.00 FS	*- FS
39	1		*REAR FENDER QUARTER GLASS INNER SHIELD	Not Necessary	60.00 FS	*- FS
40	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
41	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
42	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*60.00 FS
43	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
44	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,063.80 6,268.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					1,754.76	1,077.72
Total Parts (S\$)					9,309.04	5,190.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	1,000.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	120.00	30.00
5	REMOVE AND REFIX FENDER QUARTER GLASS	New	80.00	0.00
6	REMOVE AND REIFX REAR SPOILER	New	120.00	0.00
7	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
8	REMOVE AND REFIX FUEL TANK	New	100.00	0.00
9	REMOVE AND REFIX UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	180.00	60.00
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
11	REAR CHASSIS ALIGNMENT	New	250.00	0.00
12	TRANFER BOOTLID MECHANISM	New	80.00	60.00
13	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
14	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,920.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >