

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EG122005783/AQY3E2

**Date:** 28/07/2022

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SMX27T **Insured Vehicle No :** GBD2378C  
Date of Loss: 14/06/2022 Nature of Claim: TP Claim No: CDMCG22001153

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX27T**  
Make & Model: BMW 318I, 1.5 SEDAN LED NAV (A) Engine No: F4701215B38B15A  
Reg. Date: 25/09/2015 (Man. Year: 2015) Chassis No: WBA8E32090K497683  
Colour: Grey Odometer: 93237 km  
Engine Capacity: 1499 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/35 R20 Rear Tyre Size: 235/35 R20  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,494.90	8,754.30	13,740.60	61.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,550.00	1,910.00	2,640.00	58.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>27,044.90</b>	<b>10,664.30</b>	<b>16,380.60</b>	<b>60.57</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>27,044.90</b>	<b>8,500.00</b>	<b>18,544.90</b>	<b>68.57</b>

### INSPECTION

Date of Assignment: 17/06/2022  
Date Inspected: 17/06/2022 Inspected At: Aka Auto Pte Ltd (HQ)  
25 Kaki Bukit Road 4 #05-36 Synergy @ Kaki Bukit  
Singapore 417800  
Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2022)
<b>Parts:</b>	143	BMW 318I 1.5 SEDAN LED NAV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMX27T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR BUMPER SIDE HOLDER	Not Necessary	218.00 FL	*- FL
2	1		*REAR BUMPER TOW COVER	Not Necessary	38.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	592.00 FL	*592.00 FL
4	1		*REAR BUMPER REINFORCEMENT COVER	Cracked	225.00 FL	*225.00 FL
5	1		*REAR BUMPER CENTRE GRILLE	Cracked	192.00 FL	*192.00 FL
6	1		*REAR BUMPER SPONGE	Cracked	140.00 FL	*140.00 FL
7	1		*REVERSE SENSOR	Damaged (2pcs only)	1,000.00 FL	*500.00 FL
			(4PCS)			
8	4		*REVERSE SENSOR HOLDER	Necessary	100.00 FL	*100.00 FL
9	1		*REAR END PANEL	Repair	895.00 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Not Necessary	210.00 FL	*- FL
11	1		*TAILLAMP	O/S Cracked	1,100.00 FL	*550.00 FL
12	1		*BOOTLID	Repair	1,650.00 FL	*- FL
13	1		*BOOTLID LOCK	Not Necessary	287.00 FL	*- FL
14	1		*BOOTLID WEATHERSTRIPE	Not Necessary	169.00 FL	*- FL
15	1		*BOOTLID REFLECTOR	O/S Cut	990.00 FL	*495.00 FL
16	1		*BMW LOGO	Necessary	85.00 FL	*85.00 FL
17	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	39.00 FL	*- FL
18	1		*REAR EXHAUST PIPE GASKET	Not Necessary	35.00 FL	*- FL
19	1		*FRONT BUMPER SIDE HOLDER	Not Necessary	190.00 FL	*- FL
20	1		*FRONT BUMPER TOW COVER	Not Necessary	32.00 FL	*- FL
21	1		*FRONT BUMPER LOGO	Necessary	80.00 FL	*80.00 FL
22	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	558.00 FL	*- FL
23	2		*FRONT BUMPER SENSOR	Not Necessary	500.00 FL	*- FL
24	1		*HEADLAMP	O/S Cracked	6,136.00 FL	*3,068.00 FL
25	1		*REAR BUMPER	Deformed	2,000.00 FS	*1,400.00 FS
26	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
27	2		*REAR BUMPER REFLECTOR	Not Necessary	160.00 FS	*- FS
28	1		*REAR BUMPER LOWER DIFFUSER	Not Necessary	800.00 FS	*- FS
29	1		*SET REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
30	1		*REAR EXHAUST PIPE	Repair	2,200.00 FS	*- FS
31	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
32	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
33	1		*FRONT BUMPER	Deformed	2,000.00 FS	*1,400.00 FS
34	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
35	2		*FRONT BUMPER SIDE GRILLE	Not Necessary	400.00 FS	*- FS
36	1		*FRONT BUMPER CENTRE GRILLE	O/S Cracked	800.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>24,041.00</b>	<b>9,357.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,546.10	602.70
<b>Total Parts (\$\$)</b>	<b>22,494.90</b>	<b>8,754.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,800.00	600.00
2	SPRAY PAINTING	New	1,600.00	800.00
3	WIRING	New	100.00	60.00
4	TO SPRAY TUFF COAT	New	150.00	40.00
5	TO REMOVE REVERSE SENSOR	New	100.00	60.00
6	TO REMOVE UPHOLSTERY	New	150.00	40.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	0.00
8	TO REMOVE REAR EXHAUST PIPE	New	150.00	100.00
9	TO REMOVE FRONT BUMPER SENSOR	New	100.00	60.00
10	TO PERFORM DIAGNOSTIC TEST	New	250.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,550.00</b>	<b>1,910.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >