

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005785/KNY3Q2**Date:** 27/12/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00104422103

**Claimant Vehicle
No :** GBD7012A**Insured Vehicle
No :** YP7121H

Date of Loss: 14/06/2022

Nature of Claim: TP

Claim
No: SNM22D204194/C02/LEEPGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBD7012A**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR (M)

Engine No: 1KD2472022

Reg. Date: 20/03/2015 (Man. Year: 2014)

Chassis No: JTFHT02P300156612

Colour: Silver

Odometer: 193010 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X18

Rear Tyre Size: 195 R15X18

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,692.15	4,537.12	12,155.03	72.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,560.00	1,640.00	51.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,892.15	6,097.12	13,795.03	69.35
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	19,892.15	4,800.00	15,092.15	75.87
+ GST 7.00/7.00% (S\$)	1,392.45	336.00	1,056.45	75.87
Nett Amount (S\$)	21,284.60	5,136.00	16,148.60	75.87

INSPECTION

Date of Assignment: 17/06/2022

Date Inspected: 16/06/2022 Inspected At:

Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2022)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD7012A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Serviceable	754.00 FL	*- FL
2	2		*FRONT BUMPER SIDE RETAINER	Serviceable	299.20 FL	*- FL
3	1		*TOP CORNER PANEL N/S	Repair	485.00 FL	*- FL
4	1		*TOP CORNER PANEL GARNISH N/S	Serviceable	337.00 FL	*- FL
5	1		*HEAD LAMP N/S	Serviceable	585.00 FL	*- FL
6	1		*HEAD LAMP LOWER BRACKET N/S	Serviceable	42.00 FL	*- FL
7	1		*FRONT DOOR N/S	Bent	1,445.00 FL	*1,445.00 FL
8	1		*FRONT DOOR INNER TRIM BOARD N/S	Serviceable	586.00 FL	*- FL
9	1		*FRONT DOOR WINDOW CHANNEL N/S	Serviceable	165.00 FL	*- FL
10	1		*FRONT DOOR WINDOW REGULATOR N/S	Distorted	287.00 FL	*211.30 FL
11	1		*FRONT DOOR WINDOW REGULATOR MOTOR N/S	Jammed	399.00 FL	*399.00 FL
12	1		*FRONT DOOR WEATHERSTRIP N/S	Serviceable	185.00 FL	*- FL
13	1		*FRONT DOOR LOWER SEAL N/S	Serviceable	140.00 FL	*- FL
14	1		*FRONT DOOR PILLAR OUTER N/S	Bent	765.00 FL	*711.50 FL
15	2		*FRONT DOOR HINGE N/S	Repair	232.00 FL	*- FL
16	1		*FRONT FENDER N/S	Repair	1,156.00 FL	*- FL
17	1		*FRONT FENDER COWLING N/S	Serviceable	182.00 FL	*- FL
18	1		*SLIDING DOOR N/S	Bent	2,245.00 FL	*1,545.10 FL
19	1		*SLIDING DOOR INNER TRIM BOARD N/S	Serviceable	586.00 FL	*- FL
20	1		*FUEL TANK DOOR	Repair	465.00 FL	*- FL
21	1		*SLIDING DOOR HINGE ROLLER UPPER N/S	Serviceable	286.00 FL	*- FL
22	1		*SLIDING DOOR HINGE ROLLER LOWER N/S	Serviceable	286.00 FL	*- FL
23	1		*SLIDING DOOR WEATHERSTRIP N/S	Serviceable	185.00 FL	*- FL
24	1		*SLIDING DOOR LOWER SEAL N/S	Serviceable	140.00 FL	*- FL
25	1		*REAR BODY PANEL ROLLER RAIL N/S	Serviceable	765.00 FL	*- FL
26	1		*SLIDING DOOR STEP PANEL GARNISH N/S	Serviceable	356.00 FL	*- FL
27	1		*SLIDING DOOR STEP PANEL N/S	Repair	552.00 FL	*- FL
28	1		*REAR PANEL N/S	Repair	1,395.00 FL	*- FL
29	1		*WING MIRROR ASSY N/S	Broken	694.00 FL	*450.60 FL
30	1		*FRONT WHEEL KNUCKLE N/S	Serviceable	374.00 FL	*- FL
31	1		*FRONT WHEEL KNUCKLE BEARING N/S	Serviceable	166.00 FL	*- FL
32	1		*FRONT SHOCK ABSORBER N/S	Serviceable	415.00 FL	*- FL
33	1		*FRONT SHOCK ABSORBER MOUNTING N/S	Serviceable	97.00 FL	*- FL
34	1		*FRONT DOOR OUTER HANDLE N/S	Dented	139.00 FL	*139.00 FL
35	1		*FRONT DOOR LOCK N/S	Jammed	285.00 FL	*285.00 FL
36	1		*FRONT DOOR LOCK STRIKER N/S	Repair	45.00 FL	*- FL
37	1		*SLIDING DOOR OUTER HANDLE N/S	Dented	163.00 FL	*163.00 FL
38	1		*SLIDING DOOR LOCK N/S	Serviceable	392.00 FL	*- FL
39	1		*SLIDING DOOR LOCK SENSOR N/S	Serviceable	169.00 FL	*- FL
40	16		*FRONT BUMPER CLIPS	Not Necessary	72.00 FS	*- FS
41	1		*FRONT DOOR SPEAKER N/S	Serviceable	350.00 FS	*- FS
42	4		*HEAD LAMP N/S CLIPS	Not Necessary	18.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	8		*FRONT DOOR INNER TRIM BOARD N/S CLIPS	Not Necessary	36.00 FS	*- FS
44	6		*FRONT DOOR PILLAR INNER TRIM N/S CLIPS	Not Necessary	27.00 FS	*- FS
45	4		*FRONT STEP PANEL GARNISH N/S BOLTS	Serviceable	18.00 FS	*- FS
46	6		*FRONT WHEEL COWLING N/S CLIPS	Not Necessary	27.00 FS	*- FS
47	1		*FRONT WHEEL N/S	Serviceable	450.00 FS	*- FS
48	1		*FRONT WHEEL OUTER COVER N/S	Serviceable	120.00 FS	*- FS
49	1		*FRONT TYRE 195R15C N/S	Serviceable	280.00 FS	*- FS
50	1		*FRONT DOOR COMPANY STICKER N/S	Necessary	500.00 FS	*250.00 FS
51	1		*FRONT DOOR LTA STICKER N/S	Necessary	25.00 FS	*25.00 FS
52	8		*SLIDING DOOR INNER TRIM CLIPS N/S	Not Necessary	36.00 FS	*- FS
53	1		*SLIDING DOOR COMPANY STICKER N/S	Necessary	1,000.00 FS	*250.00 FS
54	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,253.20	5,874.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,561.05	1,337.38
Total Parts (\$\$)	16,692.15	4,537.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION.TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,200.00	700.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS	New	50.00	20.00
3	TO REMOVE AND REFIT N/S FRONT AND SLIDING DOOR COMPONENTS CHECK AND ALIGNMENT	New	100.00	60.00
4	TO DISCONNECT DOORS WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK POWER WINDOW FUNCTION	New	50.00	0.00
5	TO REMOVE AND REFIT N/S FRONT DOOR GLASS TO FACILITATE REPAIR	New	100.00	60.00
6	TO REMOVE AND REFIT N/S FRONT TYRE TO REPLACE TRIM .TO PERFORM TYRE BALANCING AND WHEEL ALIGNMENT	New	150.00	0.00
7	TO REMOVE AND REFIT N/S FRONT UNDERCARRIAGE FOR REPLACEMENT OF PARTS	New	250.00	0.00
8	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL	New	1,200.00	660.00
9	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	60.00
Gross Labour Cost (\$\$)			3,200.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >