



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 1116B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	800.00	800.00
1	REAR BUMPER LOWER	CUT	650.00	650.00
1	BUMPER BRACKET - LEFT	NOT NECESSARY	180.00	-
1	BUMPER BRACKET - RIGHT	NOT NECESSARY	180.00	-
1	BUMPER BRACKET - CENTER	NOT NECESSARY	180.00	-
1	BUMPER TRIM	CUT	400.00	400.00
2	PARKING SENSOR @\$180.00	NOT NECESSARY	360.00	-
1	REAR REINFORCEMENT BAR	NOT NECESSARY	720.00	-
1	REAR TOW HOOK COVER	CUT	60.00	60.00
	LESS 10% DISCOUNT		-353.00	-191.00
			3,177.00	1,719.00
	<u>SPECIAL NETT ITEMS</u>			
1	MISCELLANEOUS - BOLTS, NUTS, SCREWS, CLIPS, ETC (SN)	NECESSARY	50.00	30.00
			50.00	30.00
	<u>LABOUR</u>			
	REMOVE & RENEW DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS.		500.00	250.00
	RESPRAY AFFECTED AREAS.		500.00	230.00
	TO APPLY CAVITY WAX COATING ON AFFECTED AREAS. (COATING)		200.00	200.00
	LABOUR TO USE MERCEDES XANTRY TO PERFORM PARKING SENSOR CALIBRATION.		100.00	80.00
			1,300.00	760.00
	GRAND TOTAL		4,527.00	2,509.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	-----------------

Report Ref No. CS/FCI22005790/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.