#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22005791/TVY3E2

29/07/2022 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNA00155002100

**Claimant Vehicle** 

No:

SMT2688T

Insured Vehicle XE6881Z

No:

Nature of Claim: TP Date of Loss: 08/06/2022

Claim No:

CYV643066

SNM22D204182/C02/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SMT2688T Reg No:

Make & Model: VOLKSWAGEN BEETLE, 2.0 (A) Engine No:

Reg. Date: 31/01/2020 (Man. Year: 2019) Chassis No: WVWZZZ16ZKM710170

Colour: Blue Odometer: 30594 km

**Engine Capacity:** 1197 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 235/45 R16 Rear Tyre Size: 235/45 R16 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,719.71	3,093.53	626.18	16.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,190.00	3,250.00	2,940.00	47.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,909.71	6,343.53	3,566.18	35.99
+ GST 7.00/7.00% (S\$)	693.68	444.05	249.63	35.99
Nett Amount (S\$)	10,603.39	6,787.58	3,815.81	35.99

**INSPECTION** 

Date of Assignment: 27/07/2022

Volkswagen Centre Singapore (HQ)

Date Inspected: 04/07/2022 Inspected At: 247 Alexandra Road

Singapore 159934

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jul 2022)

Parts: M1-COUPE VOLKSWAGEN BEETLE 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMT2688T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FENDER	Bent	655.47 FS	*655.47 FS
1		*ALLOY WHEEL BLACK-GLOSSY	Cut	1,746.54 FS	*1,746.54 FS
1		*RUBBER VALVE	Necessary	3.85 FS	*3.85 FS
1		*REAR VIEW MIRROR HOUSING	Cut	687.67 FS	*687.67 FS
1		*MIRROR CAP PRIMED	Repair	203.38 FS	*-FS
1		*MIRROR GLASS	Not Necessary	206.72 FS	*- FS
1		*GUIDE PIECE RHS BUMPER BRACKET (SIDE)	Not Necessary	43.29 FS	*-FS
1		*GUIDE PIECE LHS BUMPER BRACKET (SIDE)	Not Necessary	43.29 FS	*-FS
1		*HOLDER FOR COVER BUMPER LH	Not Necessary	53.98 FS	*-FS
1		*HOLDER FOR COVER BUMPER RH	Not Necessary	53.98 FS	*-FS
1		*FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING	Not Necessary	21.54 FS	*-FS
iricilise	рап. 5=5рс	neu.	Total Parts (S\$)	3,719.71	3,093.53
	1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1	1 *FENDER 1 *ALLOY WHEEL BLACK-GLOSSY 1 *RUBBER VALVE 1 *REAR VIEW MIRROR HOUSING 1 *MIRROR CAP PRIMED 1 *MIRROR GLASS 1 *GUIDE PIECE RHS BUMPER BRACKET (SIDE) 1 *GUIDE PIECE LHS BUMPER BRACKET (SIDE) 1 *HOLDER FOR COVER BUMPER LH 1 *HOLDER FOR COVER BUMPER RH	1 *FENDER Bent 1 *ALLOY WHEEL BLACK-GLOSSY Cut 1 *RUBBER VALVE Necessary 1 *REAR VIEW MIRROR HOUSING Cut 1 *MIRROR CAP PRIMED Repair 1 *MIRROR GLASS Not Necessary 1 *GUIDE PIECE RHS BUMPER BRACKET (SIDE) Not Necessary 1 *GUIDE PIECE LHS BUMPER BRACKET (SIDE) Not Necessary 1 *GUIDE PIECE LHS BUMPER BRACKET (SIDE) Not Necessary 1 *HOLDER FOR COVER BUMPER LH Not Necessary 1 *HOLDER FOR COVER BUMPER RH Not Necessary 1 *FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING Not Necessary	1       *FENDER       Bent       655.47 FS         1       *ALLOY WHEEL BLACK-GLOSSY       Cut       1,746.54 FS         1       *RUBBER VALVE       Necessary       3.85 FS         1       *REAR VIEW MIRROR HOUSING       Cut       687.67 FS         1       *MIRROR CAP PRIMED       Repair       203.38 FS         1       *MIRROR GLASS       Not Necessary       206.72 FS         1       *GUIDE PIECE RHS BUMPER BRACKET (SIDE)       Not Necessary       43.29 FS         1       *GUIDE PIECE LHS BUMPER BRACKET (SIDE)       Not Necessary       43.29 FS         1       *HOLDER FOR COVER BUMPER LH       Not Necessary       53.98 FS         1       *HOLDER FOR COVER BUMPER RH       Not Necessary       53.98 FS         1       *FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING       Not Necessary       21.54 FS         nchise part. S=SpcNett.       Not Necessary       21.54 FS

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	B&P CHECK SHORT CIRCUIT / HARNESS	New	280.00	0.00
2	<b>B&amp;P DIAGNOSIS AND PROGRAMMING</b>	New	480.00	480.00
3	TO ALIGN LED HEADLIGHT	New	100.00	100.00
4	WHEEL ALIGNMENT	New	360.00	360.00
5	R&R TYRE & BALANCING	New	50.00	50.00
6	LABOUR	New	2,520.00	1,260.00
7	SPRAY PAINT	New	2,400.00	1,000.00
		Gross Labour Cost (S\$)	6,190.00	3,250.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.