

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 3755S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | HEADLAMP ASSY RH | BROKEN | 1,952.40 | 1,775.00 |
| 1 | HEADLAMP BRACKET RH | BROKEN | 39.20 | 39.20 |
| 1 | RADIATOR GRILLE | NOT NECESSARY | 899.60 | - |
| 1 | FRONT BUMPER | DENTED | 489.20 | 489.20 |
| 2 | FRONT BUMPER RETAINER RH & LH | O/S BROKEN | 35.20 | 17.60 |
| 1 | FRONT BUMPER REINFORCEMENT (REPAIR) (NPA) | NOT NECESSARY | - | - |
| 1 | FRONT BUMPER LOWER GARNISH | CRUSHED | 391.00 | 391.00 |
| 1 | FOG LAMP ASSY RH | NOT NECESSARY | 357.40 | - |
| 1 | FOG LAMP CHROME GARNISH RH | CUT | 45.90 | 45.90 |
| 1 | WASHER TANK | BROKEN | 78.90 | 78.90 |
| 1 | FRONT FENDER ARCH MOULDING RH | BROKEN | 278.40 | 278.40 |
| 1 | FRONT FENDER RH (REPAIR) (NPA) | DENTED | - | - |
| | LESS 20% DISCOUNT | | -913.44 | -623.04 |
| | | | 3,653.76 | 2,492.16 |
| 10 | FRONT BUMPER CLIPS (N) | NECESSARY | 35.00 | 30.00 |
| | LESS 20% DISCOUNT | | -7.00 | - |
| | | | 28.00 | 30.00 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRONT BUMPER LOWER GARNISH CHROME LH (SN) | NOT NECESSARY | 285.00 | - |
| | | | 285.00 | - |
| | LABOUR | | | |
| | TO KNOCK & STRAIGHTEN FRONT FENDER RH, HEADLAMP PANEL. REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION. | | 500.00 | 300.00 |
| | SPRAY PAINT FRONT BUMPER, HEADLAMP PANEL, FRONT FENDER RH. | | 500.00 | 400.00 |
| | CHECK WIRING & FOCUS HEADLIGHT. | | 30.00 | 30.00 |
| | | | 1,030.00 | 730.00 |
| | GRAND TOTAL | | 4,996.76 | 3,252.16 |

Report Ref No. CS/SPF22005793/Eqy3m4



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | 2,600.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CS/SPF22005793/Eqy3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,600.00-\$2,700.00



Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser