

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22005800/AYA3Q2**Date:** 28/04/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : GBB4873L **Insured Vehicle No :** SNA9711B

Date of Loss: 11/06/2022 Nature of Claim: TP Claim No: MFL2022D0003101

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB4873L**
 Make & Model: MITSUBISHI FB70BB1SRDEA, 3.0 D (M) Engine No: 4M42A71705
 Reg. Date: 21/04/2009 (Man. Year: 2008) Chassis No: FB70BBA10782
 Colour: White Odometer: 305898 km
 Engine Capacity: 2977 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,896.60	12,476.34	20,420.26	62.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,130.00	3,330.00	1,800.00	35.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,026.60	15,806.34	22,220.26	58.43
Approved Total (Overridden) (S\$)		12,600.00		
(S\$)	38,026.60	12,600.00	25,426.60	66.87
+ GST 7.00/7.00% (S\$)	2,661.86	882.00	1,779.86	66.87
Nett Amount (S\$)	40,688.46	13,482.00	27,206.46	66.87
+ Car Rental (28.0 x S\$50.00/day + 7.00% GST) (S\$)		1,498.00		
+ Doc/Search Fee (S\$)		38.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		15,078.45		

INSPECTION

Date of Assignment: 17/06/2022

Date Inspected: 20/06/2022 Inspected At:

Ryder Auto Pte Ltd (HQ)
2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Singapore 417921

Estimated Period of Repair: 21.0 days

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Dec 2022)	
Parts:	N/A	MITSUBISHI FB70BB1SRDEA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB4873L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	835.60 FL	*835.60 FL
2	1		*FRONT BUMPER BRACKET	Bent	266.50 FL	*266.50 FL
3	2		*FRONT O/S & N/S HEAD LAMP	Smashed	1,139.00 FL	*1,139.00 FL
4	2		*FRONT O/S & N/S SIGNAL LAMP	Cracked	639.00 FL	*639.00 FL
5	2		*FRONT O/S & N/S REFLECTOR LAMP	Smashed	492.00 FL	*492.00 FL
6	1		*FRONT O/S & N/S WIPER (NPA)	Cut	0.00 FL	*- FL
7	1		*FRONT PANEL (INNER)	Repair	2,473.30 FL	*- FL
8	1		*FRONT PANEL (OUTER)	Distorted	1,577.50 FL	*1,577.50 FL
9	1		*FRONT PANEL (OUTER)CANTER STICKER	Necessary	100.00 FS	*100.00 FS
10	2		*FRONT O/S & N/S CORNER PANEL	Distorted	1,188.00 FL	*1,188.00 FL
11	2		*FRONT O/S & N/S DOOR STICKER	Necessary	400.00 FS	*250.00 FS
12	2		*FRONT O/S & N/S DOOR COMPANY STICKER	Necessary	50.00 FS	*50.00 FS
13	1		*FRONT WIPER PANEL	Repair	546.00 FL	*- FL
14	1		*FRONT WIPER PANEL GARNISH	Cracked	642.30 FL	*642.30 FL
15	2		*FRONT O/S & N/S WIPER LINKAGE	Not Necessary	320.40 FL	*- FL
16	2		*FRONT O/S & N/S WIPER LINKAGE NOZZLE	Not Necessary	90.00 FL	*- FL
17	1		*FRONT GRILL	Cracked	510.20 FL	*510.20 FL
18	8		*FRONT GRILL CLIPS	Necessary	64.00 FS	*20.00 FS
19	1		*FRONT GRILL EMBLEM	Necessary	83.40 FL	*83.40 FL
20	1		*FRONT GRILL FUSO EMBLEM	Necessary	65.40 FL	*65.40 FL
21	1		*FRONT AIR INTAKE	Not Necessary	807.20 FL	*- FL
22	1		*FRONT HEATER	Not Necessary	3,517.20 FL	*- FL
23	1		*FRONT COOLING COIL	Cracked	1,845.60 FL	*1,455.00 FL
24	1		*FRONT BLOWER	Cracked	2,100.40 FL	*1,250.00 FL
25	1		*FRONT DASH BOARD (NPA)	Repeated	0.00 FL	*- FL
26	1		*FRONT WINDSCREEN	Cracked	1,204.30 FL	*1,204.30 FL
27	1		*FRONT WINDSCREEN SOLAR FILM	Necessary	300.00 FS	*200.00 FS
28	1		*FRONT WINDSCREEN MOULDING	Necessary	245.60 FL	*245.60 FL
29	1		*FRONT N/S SIDE MIRROR BRACKET	Bent	185.60 FL	*185.60 FL
30	1		*FRONT N/S ROUND MIRROR	Cracked	120.00 FL	*120.00 FL
31	1		*FRONT O/S DOOR	Buckled	1,310.75 FL	*1,310.75 FL
32	1		*FRONT O/S DOOR WEATHERSTRIP	Not Necessary	261.20 FL	*- FL
33	1		*FRONT O/S DOOR INNER BOARD	Not Necessary	701.70 FL	*- FL
34	8		*FRONT O/S DOOR INNER BOARD CLIPS	Necessary	40.00 FS	*30.00 FS
35	2		*FRONT O/S & N/S DOOR STEP FABRIC	Cut	303.60 FL	*303.60 FL
36	2		*FRONT O/S DOOR HINGES (UPPER & LOWER)	Not Necessary	226.80 FL	*- FL
37	1		*FRONT O/S DOOR LOCK	Jammed	365.50 FL	*365.50 FL
38	1		*FRONT O/S DOOR ACTUATOR	Not Necessary	541.20 FL	*- FL
39	1		*FRONT O/S DOOR CHECKER	Not Necessary	110.00 FL	*- FL
40	1		*FRONT O/S DOOR WINDOW REGULATOR	Not Necessary	383.40 FL	*- FL
41	1		*FRONT O/S DOOR WINDOW MOTOR	Not Necessary	485.40 FL	*- FL
42	1		*FRONT O/S DOOR WINDOW SEAL (OUTER)	Not Necessary	452.80 FL	*- FL
43	1		*FRONT O/S A PILLAR	Repair	1,578.40 FL	*- FL
44	1		*FRONT CROSS MEMBER	Not Necessary	810.40 FL	*- FL
45	1		*FRONT CABIN MOUNTING	Not Necessary	742.40 FL	*- FL
46	1		*FRONT DASHBOARD	Deformed	1,889.20 FL	*1,889.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT DASHBOARD BRACKET	Not Necessary	369.70 FL	*- FL
48	1		*BRAKE PUMP	Not Necessary	589.60 FL	*- FL
49	1		*BRAKE SERVO	Not Necessary	1,024.70 FL	*- FL
50	1		*BRAKE OIL	Not Necessary	80.00 FS	*- FS
51	1		*BRAKE PEDAL BRACKET	Not Necessary	564.70 FL	*- FL
52	1		*CLUTCH PUMP	Not Necessary	571.20 FL	*- FL
53	1		*CLUTCH PEDAL BRACKET	Not Necessary	381.10 FL	*- FL
54	1		*FRONT REG NO.PLATE BRACKET	Not Necessary	31.00 FS	*- FS
55	1		*REAR AIR DUCT	Not Necessary	810.20 FL	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					36,433.45	16,418.45
- List Item Discount on L Items 10.00/25.00% (S\$)					3,536.85	3,942.11
Total Parts (S\$)					32,896.60	12,476.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE ,REFIT & REPAIR DAMAGED PARTS	New	2,200.00	1,400.00
2	TO SPRAY PAINTING	New	1,500.00	1,200.00
3	TO REMOVE AND REPLACE FRONT DASH BOARD & WIRING	New	500.00	220.00
4	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	150.00	120.00
5	TO REMOVE AND REFIT UPHOLSTERY TO FACILITATE REPAIR	New	200.00	80.00
6	TO REMOVE AND REPLACE FRONT O/S DOOR (FITTINGS)	New	100.00	80.00
7	TO REMOVE AND REPLACE FRONT BRAKE SERVO ,CLUTCH & BLEEDING	New	200.00	150.00
8	TO CHECK FOR FAULT CODE AND RESETTNG	New	180.00	0.00
9	TO RE-SEAL ANTI-RUST	New	50.00	50.00
10	TO CHECK WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			5,130.00	3,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >