

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TP Grab Xiao Teng.
FB70BBA.

ESTIMATE OF REPAIR

Veh# : GBB4873L

Model: MITSUBISHI FB70B

Accident Date : 11/6/2022

21/4/2009-20/4/2024

Location : UPPER JURONG ROAD

3P:

(iii) SNA 9711B.

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Distorted</i>	835.60	✓	
2	1 pc	Front bumper bracket <i>Bent</i>	266.50	✓	
3	2pcs	Front o/s & n/s head lamp <i>Smashed</i>	1,139.00	✓	
4	2pcs	Front o/s & n/s signal lamp <i>Cracked</i>	639.00	✓	
5	2pcs	Front o/s & n/s reflector lamp <i>Smashed</i>	492.00	✓	
6	1 pc	Front o/s & n/s wiper <i>cut</i>		✓	
7	1 pc	Front panel (inner) <i>Repair</i>	2,473.30	x.	
8	1 pc	Front panel (outter) <i>Distorted</i>	1,577.50	✓	
9	1 pc	Front panel (outter) canter sticker <i>New</i>		100.00	✓
10	2pcs	Front o/s & n/s corner panel <i>Distorted</i>	1,188.00	✓	
11	2pcs	Front o/s & n/s door sticker <i>New</i>		400.00	250.
12	2pcs	Front o/s & n/s door company sticker <i>New</i>		50.00	✓
13	1 pc	Front wiper panel <i>Repair</i>	546.00	x.	
14	1 pc	Front wiper panel garnish <i>Cracked</i>	642.30	✓	
15	2pcs	Front o/s & n/s wiper linkage <i>Not new</i>	320.40	x	
16	2pcs	Front o/s & n/s wiper linkage nozzler <i>Not new</i>	90.00	x.	
17	1 pc	Front grill <i>Cracked</i>	510.20	✓	
18	8pcs	Front grill clips <i>2</i>		64.00	20
19	1 pc	Front grill emblem <i>New</i>	83.40	✓	
20	1 pc	Front grill FUSO emblem	65.40	✓	
21	1 pc	Front air intake <i>Not new</i>	807.2	x.	
22	1 pc	Front heater <i>Not new</i>	3517.20	x.	
23	1 pc	Front cooling coil <i>Cracked</i>	1,845.60	1435	
24	1 pc	Front blower <i>Cracked</i>	2100.40	1250	
25	1 pc	Front dash board <i>Not Requested</i>		✓	
26	1 pc	Front windscreen <i>Cracked</i>	1204.30	✓	
27	1 pc	Front windscreen solar film <i>New</i>		300.00	200
28	1 pc	Front windscreen moulding <i>New</i>	245.60	✓	
29	1 pc	Front n/s side mirror bracket <i>Bent</i>	185.60	✓	
30	1 pc	Front n/s round mirror <i>Cracked</i>	120.00	✓	
31	1pc	Front o/s door <i>Buckled</i>	1,310.75	✓	
32	1pc	Front o/s door weatherstrip <i>Not new</i>	261.20	x	
33	1pc	Front o/s door inner board <i>Not new</i>	701.70	x	
34	8pcs	Front o/s door inner board clips <i>New</i>		40.00	30
35	2 pcs	Front o/s & n/s door step fabric <i>cut</i>	303.60	✓	
36	2 pcs	Front o/s door hinges (Upper & Lower) <i>Not new</i>	226.80	x.	
37	1pc	Front o/s door lock <i>Locked</i>	365.50	✓	
38	1pc	Front o/s door actuator <i>Not new</i>	541.20	x	

39	1pc	Front o/s door checker <i>new</i>	110.00	X	
40	1pc	Front o/s door window regulator <i>new</i>	383.40	X	
41	1pc	Front o/s door window motor <i>new</i>	485.40	X	
42	1pc	Front o/s door window seal (Outer) <i>new</i>	452.80	X	
43	1pc	Front o/s A pillar <i>new</i>	1,578.40	X	
44	1 pc	Front cross member <i>new</i>	810.40	X	
45	1pc	Front cabin mounting <i>new</i>	742.40	X	
46	1 pc	Front dashboard <i>Defound</i>	1,889.20	X	
47	1 pc	Front dashboard bracket <i>new</i>	369.70	X	
48	1 pc	Brake pump <i>new</i>	589.60	X	
49	1 pc	Brake servo <i>new</i>	1,024.70	X	
50	1 pc	Brake oil <i>new</i>		80.00	X
51	1 pc	Brake pedal bracket <i>new</i>	564.70	X	
52	1 pc	Clutch pump <i>new</i>	571.20	X	
53	1 pc	Clutch pedal bracket <i>new</i>	381.10	X	
54	1 pc	Front reg. no. plate bracket <i>new</i>		31.00	X
55	1 pc	Rear air duct <i>new</i>	810.20	X	
		Sub-Total:	35,368.45	1065.00	0.00
			10%	0%	0%
		After Less %:	31,831.61	1065.00	0.00
		<i>15768.45</i>			
		<i>11826.33</i>			
		<i>SIN: 650</i>			
		Labour			
1		To dismantle, refit & repair damaged parts	2,200.00	1400	
2		To spray painting	1,500.00	1200	
3		To remove and replace front dash board & wiring	500.00	220	
4		To remove and repalce front windscreen	150.00	120	
5		TO remove and refit upholstery to facilitate repair	200.00	80	
6		To remove and replace front o/s door <i>Rtting</i>	100.00	80	
7		To remove and replace front brake servo, clutch & bleeding	200.00	150	
8		To check for fault code and resetting	180.00	X	
9		To re-seal anti-rust	50.00	✓	
10		To check wiring	50.00	30	
		Sub-Total:	5,130.00		
		Total:	38,026.61		
		After Less 20%:	30,421.28		

3280

Adrian Ling
h/s 20/06/22
21 Days

Chan San Choon
 Director
 DipEng, AAE MIMI,MSAE(Aust)


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

bizSAFE AL 8778 1999
 24 hr accident call

Mobil 1



total: 15756.33
h/s: 12.6K