

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22005806/RPA3Q2**Date:** 02/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900264133
Claimant Vehicle No :	SHB1196G	Insured Vehicle No :	SJH2900D
Date of Loss:	08/06/2022	Nature of Claim:	TP
		Claim No:	9640260615SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB1196G	Engine No:	2ZRS102744
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU403573822
Reg. Date:	28/11/2017 (Man. Year: 2017)	Odometer:	349023 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,605.30	3,995.81	5,609.49	58.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,217.00	740.00	1,477.00	66.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,822.30	4,735.81	7,086.49	59.94
Approved Total (Overridden) (S\$)		3,950.00		
Nett Amount (S\$)	11,822.30	3,950.00	7,872.30	66.59
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$70.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,552.00		
Global Sum Settlement (S\$)		4,550.00		

INSPECTION

Date of Assignment:	09/06/2022	
Date Inspected:	09/06/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM ASSY FRONT (DISC 25%)	Necessary	87.10 F	*65.33 F
2	1		*LINER ,FR FENDER ,RH (DISC 25%)	Deformed	198.40 F	*148.80 F
3	1		*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	15.00 F	*11.25 F
4	1		*WIPER WASHER JAR (DISC 25%)	Deformed	183.60 F	*137.70 F
5	1		*EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
6	1		*COVER, FR BUMPER (DISC 25%)	Torn	495.50 F	*371.63 F
7	1		*WIPER WASHER INLET (DISC 25%)	Cut	55.40 F	*41.55 F
8	1		*SUPPORT ,FR BUMPER RH (DISC 25%)	Cracked	76.90 F	*57.68 F
9	1		*UNIT HEADLAMP RH (DISC 10%)	Cracked	2,558.90 F	*2,303.01 F
10	1		*LAMP ASSY ,FOG, RH (DISC 10%)	Cracked	910.20 F	*819.18 F
11	1		*GRILLE RADIATOR	Not Necessary	165.00 F	*- F
12	1		*SUPPORT RADIATOR UPPER RH	Not Necessary	76.70 F	*- F
13	1		*NUMBER PLATE FRAME	Not Necessary	25.00 F	*- F
14	1		*EXTENSION SUB-ASSY ,LH	Not Necessary	116.30 F	*- F
15	1		*SEAL ,HOOD TO FR END	Not Necessary	24.40 F	*- F
16	1		*GRILLE SUB-ASSY	Not Necessary	335.60 F	*- F
17	1		*REINFORCEMENT FRONT UPPER	Not Necessary	691.10 F	*- F
18	1		*WIPER WASHER INLET	Not Necessary	55.40 F	*- F
19	2		*RETAINER ,FR BUMPER ,LH & RH	Not Necessary	8.50 F	*- F
20	1		*SUPPORT ,FR BUMPER LH	Not Necessary	82.30 F	*- F
21	1		*COVER ASSY ,ENGINE	Not Necessary	180.10 F	*- F
22	1		*COMPUTER SUB-ASSY ,HEADLAMP RH NO.1	Not Necessary	486.40 F	*- F
23	1		*EXTENSION SUB-ASSY ,RH	Not Necessary	116.30 F	*- F
24	1		*REINFORCEMENT FRONT LOWER	Not Necessary	238.50 F	*- F
25	1		*COVER ,ENGINE UNDER SIDE RH	Not Necessary	76.90 F	*- F
26	1		*NUMBER PLATE	Not Necessary	35.00 F	*- F
27	1		*MOTOR AND PUMP ASSY ,WINDSHIELD WASHER	Not Necessary	245.00 F	*- F
28	1		*ABSORBER ,FR BUMPER	Not Necessary	70.30 F	*- F
29	1		*SUPPORT S/A RH	Not Necessary	237.00 F	*- F
30	1		*COVER ,FR BUMPER LH	Not Necessary	28.10 F	*- F
31	1		*COVER ,FR BUMPER RH	Not Necessary	28.10 F	*- F
32	1		*PAD ,FR WHEEL RH	Not Necessary	57.70 F	*- F
33	1		*ABSORBER ,FR BUMPER LOWER	Not Necessary	117.00 F	*- F
34	1		*BRACKET ,FR BUMPER	Not Necessary	99.80 F	*- F
35	1		*SUPPORT ,FR BUMPER RH	Not Necessary	76.90 F	*- F
36	1		*SUPPORT S/A UPPER	Not Necessary	364.90 F	*- F
37	1		*FENDER SUB-ASSY ,FR, RH	Repair	933.10 F	*- F

F=Franchise part.

Total Parts (\$\$) **9,605.30** **3,995.81**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	845.00	300.00
2	SPRAY PAINT	New	936.00	400.00
3	TOWING CHARGE	New	56.00	0.00
4	TO WASH AND VACUUM	New	60.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	40.00
6	TO APPLY RUST -PPROOFING ON AFFECTED AREA	New	100.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (\$\$)			2,217.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >