

S BY 5511D 2007 Nov
Toyota Estima. 2362 CC

TP Chim.
Ashes.

AC7500052647

Front Bumper	Deformed	845.10	✓
Front Bumper Clips	✓	30(SN)	✓
Front Bumper Side Holder LH.	✓	68.50	✓
Front Bumper Fog Lamp LH.	Crushed	287.40	✓
Front Bumper Fog Lamp Cover LH.	HP ✓	127.20	X
Front Bumper Sponge	HP ✓	126.80	X
Front Bumper Reinforcement	HP ✓	471.90	X
Headlamp LH	Crushed	1912.70	✓
Front LH Fender	Dented	685.90	✓
Front LH Fender Protector	Not Rec	184.50	X
Front LH Fender Inner Shield	Torn	220.70	✓
Front LH Fender Inner Shield Clips.	New	30(SN)	✓

SBY5511D

Front LH Wheel Rim. Lt

Front LH Tyre Punched

Front LH Lower Arm. Best

Front LH Shock Absorber x 2

Front LH Knuckle Arm. Dmg

Front LH Wheel Hub c/w Bearing. Dmg

Front LH Anti Roll Bar Linkage. } x 4

Steering Rack and Pinion. m

5415.80

4061.85

~~800(SN)~~ 580(SN)

~~380(SN)~~ 200(SN)

422.80 ✓

372.50 x

559.80 ✓

412.90 ✓

165.70 x

1757.90 x

S.N : 840

Panel Beating

Spray Painting.

Wiring.

To spray tint coat

To dismantle front undercarriage

To perform wheel alignment

Towing Fees.

1350.

~~200~~ 500

~~200~~ 450

~~50~~ 30

~~150~~ 30

~~400~~ 200.

~~150~~ 80

60 ✓

Total: 6237.85

r/s : 5K.

05 Days

5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: