

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005809/APA3Q2**Date:** 28/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070166874
Claimant Vehicle No :	SMZ1455Z	Insured Vehicle No :	GBG9866Z
Date of Loss:	09/06/2022	Nature of Claim:	TP
		Claim No:	8067958245SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ1455Z		
Make & Model:	OPEL INSIGNIA GRANDSPORT B15XHT, 1.5 (A)	Engine No:	B1200760L86X0005
Reg. Date:	13/04/2021 (Man. Year: 2020)	Chassis No:	W0VZT6EB2L1028723
Colour:	White	Odometer:	20256 km
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,203.66	12,059.32	12,144.34	50.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,370.00	2,200.00	3,170.00	59.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,573.66	14,259.32	15,314.34	51.78
Approved Total (Overridden) (S\$)		11,400.00		
Nett Amount (S\$)	29,573.66	11,400.00	18,173.66	61.45
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		11,827.45		
Global Sum Settlement (S\$)		11,800.00		

INSPECTION

Date of Assignment:	10/06/2022	
Date Inspected:	10/06/2022	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,211.60 FL	*2,211.60 FL
2	1		*REAR BUMPER RETAINER (INNER)	N/S Cracked	277.40 FL	*138.70 FL
3	2		*REAR BUMPER RETAINER (OUTER)	Not Necessary	259.60 FL	*- FL
4	1		*REAR BUMPER CENTRE BRACKET	Cracked	185.60 FL	*185.60 FL
5	2		*REAR BUMPER LOWER BRACKET	Not Necessary	237.60 FL	*- FL
6	1		*REAR LOWER BUMPER	Deformed	456.80 FL	*456.80 FL
7	1		*REAR BUMPER REINFORCEMENT	Dented	831.40 FL	*831.40 FL
8	1		*REAR BUMPER SMART KEY SENSOR	Damaged	286.70 FL	*286.70 FL
9	1		*REAR BUMPER AIR VENTILATOR	Not Necessary	97.60 FL	*- FL
10	1		*REAR BUMPER TOWING COVER	Not Necessary	148.20 FL	*- FL
11	1		*REAR BUMPER REFLECTORS	N/S Cracked	247.60 FL	*123.80 FL
12	1		*REAR BUMPER BLIND SPOT SENSORS	N/S Cracked	1,975.00 FL	*987.50 FL
13	1		*REAR BLIND SPOT SENSORS BRACKETS	N/S Damaged	313.60 FL	*156.80 FL
14	2		*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	257.80 FL	*- FL
15	1		*END PANEL	Distorted	940.30 FL	*940.30 FL
16	1		*END PANEL TOP GARNISH	Cracked	280.90 FL	*280.90 FL
17	1		*END PANEL AIRDUCT	Not Necessary	186.70 FL	*- FL
18	2		*REAR FENDER INNER COWLING	Not Necessary	373.40 FL	*- FL
19	1		*REAR FENDER AIRDUCT	Not Necessary	86.90 FL	*- FL
20	1		*REVERSE SENSORS (4PCS)	Damaged (2Pcs Only)	1,112.80 FL	*556.40 FL
21	4		*REVERSE SENSORS HOLDER	Necessary	194.00 FL	*100.00 FL
22	1		*REVERSE SENSORS WIREHARDNESS (4PCS)	Snapped (1Pc Only)	2,227.20 FL	*556.80 FL
23	1		*TAILLAMP	N/S Cut	1,455.60 FL	*727.80 FL
24	2		*TAILLAMP LOWER BRACKETS	Not Necessary	375.80 FL	*- FL
25	1		*REAR BOOTLID	Dented	2,364.60 FL	*2,364.60 FL
26	1		*REAR BOOTLID INNER TRIM	Cracked	574.80 FL	*574.80 FL
27	1		*REAR BOOTLID INNER LOCK	Damaged	408.90 FL	*408.90 FL
28	1		*REAR BOOTLID LOGO	Necessary	177.60 FL	*177.60 FL
29	1		*REAR BOOTLID INSIGNIA EMBLEM	Necessary	167.80 FL	*167.80 FL
30	1		*REAR BOOTLID TURBO EMBLEM	Necessary	166.20 FL	*166.20 FL
31	1		*REAR BOOTLID WEATHERSTRIP	Not Necessary	238.90 FL	*- FL
32	1		*REAR BOOTLID LAMP	N/S Cut	1,431.60 FL	*715.80 FL
33	2		*REAR BOOTLID LAMP INNER SEALER	Necessary	76.00 FL	*38.00 FL
34	2		*REAR SILENCER BOX	Not Necessary	4,129.60 FL	*- FL
35	2		*REAR SILENCER BOX MOUNTING	Not Necessary	255.60 FL	*- FL
36	2		*REAR EXHAUST HEAT SHIELD	Not Necessary	437.80 FL	*- FL
37	1		*REAR FLOOR PANEL	Not Necessary	987.90 FL	*- FL
38	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
39	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
40	1		*SET END PANEL INSULATOR SEAL	Necessary	80.00 FS	*60.00 FS
41	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
42	1		*SET REAR FLOOR PANEL INSULATOR PAD	Not Necessary	80.00 FS	*- FS
43	1		*SET REAR NUMBER PLATE WITH CASING	Cracked	50.00 FS	*50.00 FS
44	2		*SET REAR FENDER INNER COWLING	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,847.40	13,374.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,643.74	1,315.48
Total Parts (\$\$)	24,203.66	12,059.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	New	2,000.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	1,800.00	800.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	60.00
4	TO REMOVE AND REPLACE REAR SENSOR AND DISTANCE SETTLING	New	180.00	60.00
5	TO TRANSFER AND INSTALL BOOTLID MECHANISM	New	120.00	80.00
6	TO REMOVE / INSTALL BLIND SPOT SENSOR AND SETTLING	New	500.00	250.00
7	TO APPLY SEALANT TO AFFECTED AREAS	New	300.00	0.00
8	TO REMOVE / REFIT WIRING CHECKS ON REAR TAILLAMP	New	150.00	30.00
9	TO REMOVE / REFIT REAR WINDSCREEN	New	120.00	120.00
Gross Labour Cost (S\$)			5,370.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >