8/10/22, 11:33 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22005810/APA3Q2

10/08/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993602 **Claimant Vehicle**

SMA7885H Insured Vehicle No: GW5245Z No:

Date of Loss: 08/06/2022 Nature of Claim: TP Claim No: 6152821858SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA7885H

TOYOTA VIOS, 1.5 (A) Make & Model: **Engine No:** 2NR5231287

Reg. Date: 20/06/2018 (Man. Year: 2018) Chassis No: MR2B23F3X01129212

Odometer: 108095 km Colour: Grey

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,091.35	1,272.85	1,818.50	58.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	760.00	1,820.00	70.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$	5,671.35	2,032.85	3,638.50	64.16
Approved Total (Overridden) (S\$)	1,600.00		
(\$\$	5,671.35	1,600.00	4,071.35	71.79
+ GST 7.00/7.00% (S\$) 396.99	112.00	284.99	71.79
Nett Amount (S\$	6,068.34	1,712.00	4,356.34	71.79
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/06/2022

SM Automotive (HQ)

756 JURONG WEST STREET 74, #12-60 Date Inspected: 13/06/2022 Inspected At:

Singapore 640756

Estimated Period of Repair: 3.0 days

ADRIAN LING CHEW HSIAO TONG Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	591.00 FL	*591.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	89.00 FL	*89.00 FL
3	2		*LH REAR FENDER	Repair	878.00 FL	*- FL
4	1		*LH REAR FENDER INNER COWLING	Not Necessary	62.00 FL	*- FL
5	1		*LH REAR TAILLAMP	Cracked	351.00 FL	*351.00 FL
6	1		*LH REAR WHEEL BEARING WITH HUB	Not Necessary	378.00 FL	*- FL
7	1		*LH REAR REFLECTOR	Cracked	92.80 FL	*92.80 FL
8	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
9	1		*LH REAR SPORT RIM	Cut	850.00 FS	*400.00 FS
10	1		*LH REAR TYRE	Not Necessary	280.00 FS	*- FS
11 5-5-0	1	nort C=CnoN	*LH REAR FENDER INNER COWLING CLIPS lett. L=ListItemDisc.	Not Necessary	50.00 FS	*-FS
г-гіа	iricilise	ран. Э-Эрск	- List Item Discount on L Ite	Sub Total (S\$)	3,701.80 610.45	1,553.80 280.95
			- List Roll Biscoult on E Ro			
				Total Parts (S\$)	3,091.35	1,272.85
			Report was unsubmitted during th	is print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR FOR PANEL BEATING	New	1,000.00	300.00
2	LABOUR FOR SPRAY PAINTING	New	1,000.00	400.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	300.00	30.00
5	LABOUR FOR REMOVE & RENEW LH REAR WHEEL BEARING	New	200.00	0.00
	Gross Labour Cost (S\$)		2,580.00	760.00
	Report was unsubmitted during t	his print-out.		

< END OF ESTIMATES >