

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 2965J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TORN	1,051.80	693.00
2	REAR BUMPER SIDE RETAINER @\$84.50	NOT NECESSARY	169.00	-
1	REAR BUMPER REINFORCEMENT	DENTED	365.80	365.80
2	REAR BUMPER REINFORCEMENT BRACKET @\$105.80	DISTORTED	211.60	211.60
	LESS 10% DISCOUNT		-179.82	-127.04
			1,618.38	1,143.36
	SPECIAL NETT ITEMS			
1	REAR BUMPER TOP STAINLESS PLATE (SN)	DEFORMED	203.90	203.90
1	SET REVERSE PARKING SENSOR (SN)	MALFUNCTION	351.20	351.20
1	REVERSE PARKING SENSOR CONTROLLER BOX (SN)	MALFUNCTION	118.50	118.50
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
			733.60	703.60
	<u>LABOUR</u>			
	REMOVE & REPLACE REVERSE SENSOR.		150.00	50.00
	TO REPAIR END PANEL & REPLACE DAMAGED PART.		1,200.00	500.00
	SPRAY PAINT ON AFFECTED PARTS.		900.00	400.00
			2,250.00	950.00
	GRAND TOTAL		4,601.98	2,796.96

RECOMMENDED COST OF REPAIRS	2,796.96
-----------------------------	----------

Report Ref No. CS3/SMR22001970/Eqy3n2-1

CHEN TSUE YEE

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator