

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

601, Choa Chu Kand Street 62, # 04-07, Singapore 680601

E-mail address: aassehec@gmail.com

Mobile Number: 96623655

RCB No. 43037800M

VEHICLE INSPECTION REPORT

To:	Cheong Chun Kit Joel c/o Lye Designs 10, Ang Mo Kio Industrial Park 2A # 04-04, AMK Auto Point Singapore 568047	Report No :	TP/0006/05/2022
		Date :	09 May 2022

REFERENCE

Requested by :	Cheong Chun Kit Joel	3rd Party Vehicle No. :	SMM 7145Y
Date of Request :	06 January 2022	Owner's Vehicle No. :	SKV 5231X
Date of Accident :	03 January 2022	Sum Insured :	Not Available
Date Inspected :	06 January 2022	Policy No. :	Not Available
Inspected at :	Lye Designs	Claim No. :	Not Available

PARTICULARS OF VEHICLE

Reg. No. :	SKV 5231X	Vehicle Model :	Prius Hybrid 1.8L G'S A	Air Conditioner :	Yes
Vehicle Make :	Toyota	Engine No. :	2ZR6297950	Radio/Cassette :	Yes
Original Regn Date :	22 September 2015	Chassis No. :	ZVW305757972	Seat Belt :	Yes
Lifespan Expiry Date :	-----	Propellant :	Petrol	Colour :	White
COE Expiry Date :	21 September 2025	Engine Capacity :	1,798 cc	Speedometer :	100,600 km

CONDITION OF TYRES

	MAKE	SIZE	RIM	% REMAINING
Right Front :	Yokohama	225/45 ZR17	Sport Rim	70%
Left Front :	Yokohama	225/45 ZR17	Sport Rim	70%
Right Rear :	Yokohama	225/45 ZR17	Sport Rim	70%
Left Rear :	Yokohama	225/45 ZR17	Sport Rim	70%

DESCRIPTION OF DAMAGES

NOTE: The above vehicle was SURVEYED WITHOUT PREJUDICE

The owner's vehicle sustained damages on the frontal LH portions.

Estimated period of repairs: 3 (Three) working days

Repairer completed the repair in: 03 (Three) days inclusive of Sunday and Public Holiday

06 January 2022 to 07 March 2022 - 58 days pending for spare parts (Owner is still driving the vehicle)

08 March 2022 to 05 May 2022 - 59 days pending for spare parts - Body Sticker (Owner is still driving the vehicle)

Number of photographs taken at time of inspection and attached: 16 (Sixteen) + 08 (Eight) Follow up Survey (After Dismantling & Damaged Parts, 08 (Eight) Follow-up Survey (Before Painting) and 08 (Eight) Follow-up Survey (After Repair/Painting And Damaged Parts) only.

SUMMARY OF REPAIR COSTS

Repairer's Estimate	\$ 7,458.60
Revised Parts	\$ 4,579.70
Revised Labour	\$ 680.00
Total Revised Amount	\$ 5,259.70
Adjusted Amount	\$ 5,259.70
Less: Owner's Excess	\$ N.A.
Total	\$ 5,259.70
Net Total without GST	\$ 5,259.70

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUAN (HP 96623655)
ENG TECH. / AIE MIMI / AM SAE-A

P/P
3 days

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

601, Choa Chu Kang Street 62, # 04-07, Singapore 680601

E-mail Address: aasschee@gmail.com

Mobile Number: 96623655

RCB No. 43037800M

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No: **SKV 5231X**

Attachment to report no.: TP/0006/05/2022

REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS	
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price	Conditions	S\$ Price
REPLACEMENT OF DAMAGED PANELS/PARTS		LUMP SUM REPAIR	LESS 25%
01. 1 pc front bumper	2,379.60	Dented - To replace	2,379.60
02. 1 pc front bumper rubber seal	105.00	Necessary / Damage if removed - To replace	105.00
03. 1/2 pcs front bumper side retainer @ 261.00 LH	522.00	Bent - To replace LH only	261.00
04. 1 pc front bumper lower	261.00	Dented - To replace	261.00
05. 1 pc front bumper grille	291.00	Cracked - To replace	291.00
06. 1 pc front bumper LH fog lamp garnish	108.00	Dented - To replace	108.00
07. 1 pc front bumper towing cover	27.00	Serviceable - To reuse	0.00
08. 1 pc front LH headlamp	2,034.00	Cracked - To replace	2,034.00
09. 1 pc front under tray	351.00	Serviceable - To reuse	0.00
	-----		-----
	6,078.60		5,439.60
			1,359.90

			4,079.70
10. 1 pc front bumper sticker	S.Net 500.00	Necessary / Damage if removed - To replace	500.00
		(Come in set for the whole vehicle)	
	-----		-----
	6,578.60		4,579.70
	-----		-----

Less 25%

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUAN (HP. 96623655)
ENG TECH, CAE MIMI / AM SAE-A
MSAAA/Accident Damage Appraiser

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

601, Choa Chu Kang Street 62, # 04-07, Singapore 680601

E-mail Address: aasschee@gmail.com

Mobile Number: 96623655

RCB No. 43037800M

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No: **SKV 5231X**

Attachment to report no.: TP/0006/05/2022

REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS	
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price	Conditions	S\$ Price
LABOUR CHARGES			
01. Labour Charges - Panel beating	500.00	Necessary - Reason being: 01. To remove damaged parts and attachments repair and reshape dented panels, renew damaged panels and parts (refer to our recommendations) align and refit attachments. (inclusive of redoing body sticker).	400.00 240
02. Labour charges - Spray Painting	300.00	Necessary Reason being: 01. To respray paint on front bumper and other affected areas.	250.00 ✓
03. Labour charges - Anti rust coating	50.00	Not Necessary Reason being: 01. Not Necessary to apply/respray anti rust proofing.	0.00
04. Labour charges - Lighting system	30.00	Necessary Reason being: 01. To check lighting system and focus from headlamps.	30.00
	880.00		680.00

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUAN (HP. 96623655)
ENG TECH, CAE MIMI / AM SAE-A
MSAAA/Accident Damage Appraiser