

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 5231X

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER | DENTED | 2,379.60 | 1,250.00 |
| 1 | FRONT BUMPER RUBBER SEAL | SERVICEABLE | 105.00 | - |
| 2 | FRONT BUMPER SIDE RETAINER @\$261.00 | N/S BENT | 522.00 | 95.00 |
| 1 | FRONT BUMPER LOWER | NOT NECESSARY | 261.00 | - |
| 1 | FRONT BUMPER GRILLE | NOT NECESSARY | 291.00 | - |
| 1 | FRONT BUMPER LH FOG LAMP GARNISH | DENTED | 108.00 | 108.00 |
| 1 | FRONT BUMPER TOWING COVER | SERVICEABLE | 27.00 | - |
| 1 | FRONT LH HEADLAMP | CRACKED | 2,034.00 | 980.00 |
| 1 | FRONT UNDER TRAY | SERVICEABLE | 351.00 | - |
| | LESS 25% DISCOUNT | | - | -608.25 |
| | | | 6,078.60 | 1,824.75 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRONT BUMPER STICKER (SN) | NECESSARY | 500.00 | 200.00 |
| | | | 500.00 | 200.00 |
| | <u>LABOUR</u> | | | |
| | LABOUR CHARGES - PANEL BEATING. | | 500.00 | 200.00 |
| | REASON BEING: 01.TO REMOVE DAMAGED PARTS AND ATTACHMENTS REPAIR AND RESHAPE DENTED PANELS, RENEW | | | |
| | DAMAGED PANELS AND PARTS (REFER TO OUR RECOMMENDATIONS) ALIGN AND REFIT ATTACHMENTS. (INCLUSIVE OF REDOING BODY STICKERS). | | | |
| | LABOUR CHARGES - SPRAY PAINTING. REASON BEING: 01. TO RESPRAY PAINT ON FRONT BUMPER AND OTHER AFFECTED AREAS. | | 300.00 | 250.00 |
| | LABOUR CHARGES - ANTI RUST COATING. REASON BEING: 01. NOT NECESSARY TO APPLY / RESPRAY ANTI RUST PROOFING. | NOT NECESSARY | 50.00 | - |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,504.75

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-----------|-------------------------------|-------------------|
| 1 | LABOUR CHARGES - LIGHTING SYSTEM. REASON BEING: 01. TO CHECK LIGHTING SYSTEM AND FOCUS FRONT HEADLAMPS. | | 30.00 | 30.00 |
| | | | 880.00 | 480.00 |
| | GRAND TOTAL | | 7,458.60 | 2,504.75 |

RECOMMENDED COST OF REPAIRS

Report Ref No. CS3/AIG22000137/Gty3e2-1

XING GUO QIANG

ANG BRYAN TANI

Automotive Assessor / Investigator

M.MATAI, AMSAE-A
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.