

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005816/KYA3Q2**Date:** 08/06/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070119441
Claimant Vehicle No :	SNF2700C	Insured Vehicle No :	SMU5621K
Date of Loss:	15/06/2022	Nature of Claim:	TP
		Claim No:	7701600262SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF2700C	Engine No:	DJU001364
Make & Model:	PORSCHE 718 BOXSTER GTS, 2.5 (A)	Chassis No:	WP0ZZZ98ZJS221249
Reg. Date:	04/07/2018 (Man. Year: 2018)	Odometer:	14661 km
Colour:	Metallic Dark Blue		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35Z R20	Rear Tyre Size:	265/35Z R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,288.00	3,062.79	14,225.21	82.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,870.00	730.00	1,140.00	60.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,158.00	3,792.79	15,365.21	80.20
+ GST 7.00/7.00% (S\$)	1,341.06	265.50	1,075.56	80.20
Nett Amount (S\$)	20,499.06	4,058.29	16,440.77	80.20
+ Car Rental (2.0 x S\$120.00/day + 7.00% GST) (S\$)		256.80		
		(S\$)	4,315.09	
Liabile Amount (80.00%) (S\$)		3,452.07		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,454.07		
Global Sum Settlement (S\$)		3,400.00		

INSPECTION

Date of Assignment:	20/06/2022		Optima Werkz Pte Ltd (HQ)
Date Inspected:	20/06/2022	Inspected At:	10 ANG MO KIO INDUSTRIAL PARK 2A
			#01-05 AMK AUTOPOINT
			SINGAPORE 568047
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,300.00 FL	*- FL
2	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	270.00 FL	*- FL
3	1		*REAR FENDER RH	Repair	8,640.00 FL	*- FL
4	1		*REAR RIM RH	Dented	4,050.00 FL	*3,053.10 FL
5	1		*REAR ABSORBER RH	Serviceable	1,360.00 FL	*- FL
6	1		*REAR LOWER ARM RH	Serviceable	1,360.00 FL	*- FL
7	1		*REAR TIE ROD RH	Serviceable	640.00 FL	*- FL
8	1		*REAR BUMPER CLIPS	Not Necessary	80.00 FS	*- FS
9	1		*REAR RH TYRE (70%)	Cut	450.00 FS	*315.00 FS
					Sub Total (\$)	19,150.00 3,368.10
					- List Item Discount on L Items 10.00/10.00% (\$)	1,862.00 305.31
					Total Parts (\$)	17,288.00 3,062.79

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	600.00	200.00
2	LABOUR CHARGES FOR PAINTING TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER ,REAR FENDER RH & ETC	New	600.00	440.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR ABSORBER RH ,REAR LOWER ARM RH ,REAR TIE ROD RH & ETC	New	300.00	0.00
4	LABOUR CHARGES TO REMOVE & REPLACE REAR RIM RH	New	150.00	30.00
5	TO WHEEL ALIGNMNET & BALANCING	New	100.00	60.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM	New	120.00	0.00
Gross Labour Cost (\$\$)			1,870.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >