

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22005821/UQY3N2**Date:** 24/06/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000690496-01

Claimant Vehicle No : SKX1971J **Insured Vehicle No :** SLV1068R

Date of Loss: 10/06/2022 Nature of Claim: TP Claim No: 202222005235/KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX1971J**

Make & Model: HONDA MOBILIO, 1.5 RS Luxe (A) Engine No: L15Z12101153

Reg. Date: 30/11/2015 (Man. Year: 2015) Chassis No: MRHDD4870FP000329

Colour: Orange Odometer: 105638 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15

Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	856.00	881.10	-25.10	-2.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	620.00	500.00	44.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,976.00	1,501.10	474.90	24.03
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	1,976.00	1,050.00	926.00	46.86
+ GST 7.00/7.00% (S\$)	138.32	73.50	64.82	46.86
Nett Amount (S\$)	2,114.32	1,123.50	990.82	46.86

INSPECTION

Date of Assignment: 17/06/2022

Date Inspected: 20/06/2022 Inspected At: Tan Lim Motor Pte Ltd (Defu)

1 Defu Lane 6

Singapore 539365

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jun 2022)
Parts:	M1-MPV	HONDA MOBILIO 1.5 RS Luxe (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX1971J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S FRONT HEADLAMP (WCP)	Holder Cracked	520.00 F	*520.00 F
2	1		*FRONT BUMPER (WCP)	Deformed	190.00 F	*190.00 F
3	10		*FRONT BUMPER CLIP (WCP)	Necessary	18.00 F	*18.00 F
4	1		*N/S FRONT BUMPER SIDE RETAINER (WCP)	Bent	13.00 F	*13.00 F
5	1		*FRONT BUMPER LOWER CENTER GRILLE (WCP)	Not Necessary	55.00 F	*- F
6	1		*N/S FOG LAMP COVER (WCP)	Grazed	60.00 F	*60.00 F
F=Franchise part.						
Sub Total (\$\$)					856.00	801.00
+ Margin on L,N Items 0.00/10.00% (\$\$)					0.00	80.10
Total Parts (\$\$)					856.00	881.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	500.00	300.00
2	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	500.00	300.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	60.00	0.00
Gross Labour Cost (S\$)			1,120.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >