

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005822/UPA3Q2**Date:** 27/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000001654
Claimant Vehicle No :	SDW5905M	Insured Vehicle No :	SLK850M
Date of Loss:	16/06/2022	Nature of Claim:	TP
		Claim No:	0372076358SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDW5905M	Engine No:	1ZRY301719
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104552437
Reg. Date:	16/09/2016 (Man. Year: 2016)	Odometer:	86177 km
Colour:	Brown		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,207.05	472.65	734.40	60.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	710.00	530.00	180.00	25.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,917.05	1,002.65	914.40	47.70
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	1,917.05	800.00	1,117.05	58.27
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,002.00		

INSPECTION

Date of Assignment:	20/06/2022		
Date Inspected:	20/06/2022	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Dented / Deformed	582.20 FL	*582.20 FL	
2	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL	
3	1		*REAR BUMPER REINFORCEMENT	Repair	362.20 FL	*- FL	
4	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	388.20 FL	*- FL	
5	2		*REAR BUMPER O/S & N/S SIDE RETAINER	Not Necessary	228.80 FL	*- FL	
					Sub Total (\$)	1,609.40	630.20
					- List Item Discount on L Items 25.00/25.00% (\$)	402.35	157.55
					Total Parts (\$)	1,207.05	472.65

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP FOR REVERSE SENSOR	New	30.00	30.00
2	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	300.00	200.00
3	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED PARTS	New	380.00	300.00
			Gross Labour Cost (\$\$)	710.00
				530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >