

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22005823/UNY3E2**Date:** 18/10/2022**REFERENCE**

Insured/Claimant: YI HE FA ENTERPRISES Policy No: DMCVSNW00019062201

Date of Loss: 11/06/2022

Nature of Claim: OD

Claim No: SNM22D204129/C01/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBJ2341B**

Make & Model: ISUZU TFR86JSR, 2.5 D (M)

Reg. Date: 25/02/2019 (Man. Year: 2018)

Colour: White

Engine Capacity: 1898 cc

Market Value/New Car Price: S\$58,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: TD0896

Chassis No: MPATFR87JJT001413

Odometer: 41763 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/70 R15

Front Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

Rear Tyre Size: 215/70 R15

Rear Left Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,660.00	6,855.00	-2,195.00	-47.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,648.21	1,627.21	21.00	1.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,308.21	8,482.21	-2,174.00	-34.46
Approved Total (Overridden) (S\$)		7,000.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	6,308.21	6,500.00	-191.79	-3.04
+ GST 7.00/7.00% (S\$)	441.57	455.00	-13.43	-3.04
Nett Amount (S\$)	6,749.78	6,955.00	-205.22	-3.04

INSPECTION

Date of Assignment: 17/06/2022 Present Location: Jin Auto Services Pte Ltd (Defu)
Jin Auto Services Pte Ltd (Defu)
Date Inspected: 20/06/2022 Inspected At: Blk 14 Defu Lane 10, #01-410/412
Singapore 539195
Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Oct 2022)	
Parts:	N/A	ISUZU TFR86JSR 2.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ2341B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTA PARTS		4,660.00 F	*5,295.00 F
2	1		*AIR COOLER	Cracked	-	*980.00 F
3	1		*EXPANSION TANK	Distorted	-	*85.00 F
4	1		*INN GRILLE MOULDING	Cracked	-	*180.00 F
5	1		*L/F BUMP REINF BRKT	Bent	-	*40.00 F
6	1		*L/F ENGINE MOUNTING	Torn	-	*40.00 F
7	1		*L/LOWER RUBBER	Torn	-	*35.00 F
8	1		*LWR RADIATOR GRILLE	Cracked	-	*200.00 F

F=Franchise part.

Total Parts (S\$)	4,660.00	6,855.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL LABOUR	New	764.40	743.40
2	TOTAL PAINT	New	883.81	883.81
3	TOTAL PAINT (NPA) (REPEATED)	New	-	0.00
Gross Labour Cost (\$\$)			1,648.21	1,627.21

Report was unsubmitted during this print-out.

< END OF ESTIMATES >