

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22005825/UYA3Q2
Date: 26/05/2023

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100497021
Claimant Vehicle No : GBJ8390U **Insured Vehicle No :** SLJ2260H
Date of Loss: 18/04/2022 Nature of Claim: TP Claim No: 7165706662SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ8390U**
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR (M) Engine No: 1KD2868521
Reg. Date: 03/09/2019 (Man. Year: 2019) Chassis No: JTFHT02P000249491
Colour: White Odometer: 135971 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,539.60	1,048.20	1,491.40	58.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	620.00	160.00	20.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,319.60	1,668.20	1,651.40	49.75
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	3,319.60	1,300.00	2,019.60	60.84
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
Nett Liability (S\$)		1,540.00		

INSPECTION

Date of Assignment: 20/06/2022
Date Inspected: 20/06/2022 Inspected At: Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)
Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	796.80 F	*796.80 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*FRONT BUMPER BRACKET LH	Cracked	178.00 F	*178.00 FL
4	1		*FRONT STEP GARNISH	Torn	372.80 F	*372.80 FL
5	1		*SET FRONT STEP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
6	1		*FRONT HEAD LAMP	Serviceable	930.70 F	*- FL
7	1		*SET FRONT HEAD LAMP CLIP	Not Necessary	65.00 FS	*- FS
8	1		*FRONT HEAD LAMP BRACKET	Not Necessary	116.30 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,539.60	1,397.60
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	349.40
Total Parts (\$\$)	2,539.60	1,048.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	400.00	300.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	300.00	300.00
3	TO APPLY RUST PROOFING ,RESEAL TUFF -COATING TREATMENT ON ACCIDENT AREA	New	40.00	0.00
4	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	40.00	20.00
Gross Labour Cost (\$\$)			780.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >