

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: G13783904  
 at Workshop m/s: 123 RD  
 of \_\_\_\_\_  
 Insured: SLJ 2260H  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$73k.  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS C 196N  
 Date: \_\_\_\_\_ Person Contacted: LIA 17089  
 Vehicle: IN / OUT

Veh No: G13783904 Yr Regn: 03/09/19  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or Car  
 Make: Toyota c.c. 2982  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 135971 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTFHT02P000249491  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195 R15  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front 6 Rear 6  
 R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm  
 L/Bal. 0 mm L/Bal. 6 mm  
 D.O.A. 18/04/22 D.O.I. 20/06/22  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or  
N/S Rep.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
28/6/22 2/s \$1300 Rep OK. informed Susan.

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 2  
 Resurvey No. of Trip: \_\_\_\_\_

1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$ )

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 ) S + RS, SI  
 ) Photos  
 ) Others  
 TOTAL \_\_\_\_\_

AIG Asia Pacific Insurance Pte Ltd  
 Motor Claims Department  
 78 Shenton Way #07-16  
 AIG Building Singapore 079120

Ref Date:  
 Ref No:  
 Vehicle No:  
 Model / Make:

**ESTIMATE**  
 17-06-2022  
 GBJ8390U220418  
 GBJ8390U  
 Toyota Hiace  
 Van Turbo 5DR MT

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Front	Bumper	\$ 796.80	1	\$ 796.80		/
2		Bumper Clips 1 set	\$ 50.00	1	\$ 50.00	SN	/
3		Bumper Bracket Lh	\$ 178.00	1	\$ 178.00		/
4		Step Garnish	\$ 372.80	1	\$ 372.80		/
5		Step Garnish Clips 1 set	\$ 30.00	1	\$ 30.00	SN	X
6		Head Lamp	\$ 930.70	1	\$ 930.70		X
7		Head Lamp Clip 1 set	\$ 65.00	1	\$ 65.00	SN	X
8		Head Lamp Bracket	\$ 116.30	1	\$ 116.30	SN	X
9		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 400.00		300
10		To putty & spray painting & including touch up paint on accident affected areas			\$ 300.00		/
11		To apply Rust Proofing , reseal tuff-coating treatment on accident area			\$ 40.00	11	X
12		To check all wiring & electrical component for proper function			\$ 40.00		20
					\$		

Total Parts & Labour of estimate for damaged vehicle

\$ 3,319.60

Total amount in Lumpsum Basis for repaired vehicle

\$ -

SDL

*not authorized  
 here  
 1/3 \$ 1300  
 20/06/22  
 3 days*



Liu's Bro Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*P-13976  
 252  
 1048.2  
 620  
 1668.20  
 20%  
 1374*