

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005829/APA3Q2**Date:** 22/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800046339
Claimant Vehicle No :	SMJ7935A	Insured Vehicle No :	SMA795E
Date of Loss:	11/06/2022	Nature of Claim:	TP
		Claim No:	4301969647SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ7935A		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UHN8803
Reg. Date:	21/03/2019 (Man. Year: 2018)	Chassis No:	MMBSTA13AKH001147
Colour:	Red	Odometer:	42074 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,024.00	5,704.60	4,319.40	43.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	3,170.00	770.00	19.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,964.00	8,874.60	5,089.40	36.45
Approved Total (Overridden) (S\$)		7,100.00		
Nett Amount (S\$)	13,964.00	7,100.00	6,864.00	49.15
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
Nett Liability (S\$)		8,100.00		

INSPECTION

Date of Assignment:	14/06/2022	
Date Inspected:	14/06/2022 Inspected At:	Tk Motor Workshop (HQ) Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt Singapore 417883
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	828.00 F	*828.00 FN
2	1		*REAR BOOTLID LOCK	Damaged	206.00 F	*206.00 FN
3	1		*REAR BOOTLID RUBBER	Cut	148.00 F	*148.00 FN
4	1		*REAR ATTRAGE EMBLEM	Necessary	38.00 F	*38.00 FN
5	1		*REAR MIT EMBLEM	Necessary	41.00 F	*41.00 FN
6	1		*REAR MIVEC EMBLEM	Necessary	40.00 F	*40.00 FN
7	1		*C&C EMBLEM	Necessary	35.00 F	*35.00 FN
8	1		*REAR BOOTLID CHROME MOULDING	Not Necessary	318.00 F	*- FN
9	2		*REAR BOOTLID HINGE	Not Necessary	384.00 F	*- FN
10	1		*REAR BOOTLID SPOILER LID	Not Necessary	380.00 FS	*- FS
11	1		*REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
12	2		*REAR TAILLAMP	Cut	592.00 F	*592.00 FN
13	8		*REAR TAILLAMP CLIP	Necessary	40.00 F	*20.00 FN
14	1		*REAR L/H TAILLAMP PANEL	Buckled	170.00 F	*170.00 FN
15	1		*REAR L/H FENDER	Buckled	725.00 F	*725.00 FN
16	1		*REAR R/H FENDER	Repair	725.00 F	*- FN
17	1		*REAR (R/H & L/H) FENDER INNER TRIMBOARD	N/S Torn	360.00 F	*180.00 FN
18	1		*REAR END PANEL	Dented	465.00 F	*465.00 FN
19	1		*REAR END PANEL LOCK	Not Necessary	38.00 F	*- FN
20	1		*REAR END PANEL GARNISH	Deformed	68.00 F	*68.00 FN
21	4		*REAR END PANEL GARNISH CLIP	Necessary	20.00 F	*20.00 FN
22	1		*REAR END PANEL AIR GRILLE GARNISH	Deformed	45.00 F	*45.00 FN
23	1		*REAR END PANEL AIR GRILLE COVER GARNISH	Deformed	42.00 F	*42.00 FN
24	2		*REAR END PANEL AIR GRILLE COVER GARNISH CLIP	Necessary	10.00 F	*10.00 FN
25	1		*REAR BUMPER	Distorted	728.00 F	*728.00 FN
26	2		*REAR BUMPER SIDE RETAINER	Damaged	72.00 F	*72.00 FN
27	8		*REAR BUMPER CLIP	Necessary	40.00 F	*40.00 FN
28	2		*REAR BUMPER REFLECTOR	Cracked	76.00 F	*76.00 FN
29	1		*REAR BUMPER LOWER SKIRT	Distorted	850.00 FS	*750.00 FS
30	2		*REAR BUMPER SIDE INNER SHIELD GARNISH	Torn	56.00 F	*56.00 FN
31	4		*REAR BUMPER SIDE GARNISH CLIP	Necessary	20.00 F	*20.00 FN
32	1		*SET REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
33	1		*SPARE WHEEL BOARD	Torn	228.00 F	*228.00 FN
34	1		*KEYLESS SENSOR	Damaged	110.00 F	*110.00 FN
35	1		*KEYLESS SENSOR BRACKET	Not Necessary	12.00 F	*- FN
36	1		*ANTENNA SENSOR	Damaged	116.00 F	*116.00 FN
37	2		*REAR END PANEL INNER SIDE GARNISH	Not Necessary	316.00 F	*- FN
38	6		*REAR END PANEL INNER SIDE GARNISH CLIP	Not Necessary	30.00 F	*- FN
39	1		*SPARE TYRE PANEL	Repair	916.00 F	*- FN
40	1		*REAR WINDSCREEN MOULDING	Necessary	85.00 F	*85.00 FN
41	1		*REAR WINDSCREEN INNER SEAL	Necessary	26.00 FS	*26.00 FS
42	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	10,024.00	6,225.00
- Nett Item Discount on N Items 0.00/10.00% (\$)	0.00	520.40
Total Parts (\$)	10,024.00	5,704.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY PAINTING (PEARL RED)	New	1,800.00	1,400.00
3	TO REMOVE & REFIG REAR INTERIOR UPHOSLY	New	150.00	60.00
4	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	New	80.00	80.00
5	TO MEASURE & DRILL REAR BUMPER ,POSITION & INSTALL REAR REVERSE SENSOR ,REAR CAMERA ,CONTROL UNIT ,CHECK & TEST FOR FUNCTIONING	New	80.00	80.00
6	TO PANEL BEATING ,WELDING REMOVE ALL DAMAGE PARTS & REPLACING OF THE NEW PARTS ETC	New	1,600.00	1,400.00
7	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
Gross Labour Cost (S\$)			3,940.00	3,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >