

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22005830/RPA3Q2**Date:** 01/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100401270
<b>Claimant Vehicle No :</b>	SG5823Y	<b>Insured Vehicle No :</b>	SJQ1122S
Date of Loss:	27/05/2022	Nature of Claim:	TP
		Claim No:	8286238348SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SG5823Y</b>	Engine No:	50344580424459
Make & Model:	MAN A95, 10.5 D (A)	Chassis No:	WMAA95ZZ4G7003478
Reg. Date:	21/08/2017 (Man. Year: 2016)	Odometer:	367492 km
Colour:	Green		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8/8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,707.00	1,272.00	435.00	25.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>1,707.00</b>	<b>1,272.00</b>	<b>435.00</b>	<b>25.48</b>
<b>+ Loss of Use (2.5 x S\$275.00/day) (S\$)</b>		687.50		
<b>+ Doc/Search Fee (S\$)</b>		1.87		
<b>Nett Liability (S\$)</b>		<b>1,961.37</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,950.00</b>		

INSPECTION

Date of Assignment:	15/06/2022	
Date Inspected:	15/06/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR REAR RHS PORTION	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	432.00	262.00
3	ADVERTISEMENT STICKER	New	480.00	480.00
<b>Gross Labour Cost (\$)</b>			<b>1,707.00</b>	<b>1,272.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >