

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22005836/APA3Q2**Date:** 03/10/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7220059571   |
| <b>Claimant Vehicle No :</b> | SNA6507U                             | <b>Insured Vehicle No :</b> | SNF4326L     |
| Date of Loss:                | 14/06/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 6362600283SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                            |             |                   |
|-----------------------------|--------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SNA6507U</b>                            |             |                   |
| Make & Model:               | TOYOTA VELLFIRE, 2.5 ELEGANCE MOONROOF (A) | Engine No:  | 2ARJ288929        |
| Reg. Date:                  | 21/01/2020 (Man. Year: 2019)               | Chassis No: | JTNGF3DH408022465 |
| Colour:                     | White                                      | Odometer:   | 71060 km          |
| Engine Capacity:            | 2494 cc                                    |             |                   |
| Market Value/New Car Price: | N/A                                        |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>          |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 235/50 R18  | Rear Tyre Size:  | 235/50 R18  |
| Front Left Side:  | Dunlop 6 mm | Rear Left Side:  | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 8,199.89          | 3,187.60          | 5,012.29          | 61.13         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 4,130.00          | 1,600.00          | 2,530.00          | 61.26         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>              | <b>12,329.89</b>  | <b>4,787.60</b>   | <b>7,542.29</b>   | <b>61.17</b>  |
| <b>Approved Total (Overridden) (S\$)</b>         |                   | <b>3,800.00</b>   |                   |               |
| <b>(S\$)</b>                                     | 12,329.89         | 3,800.00          | 8,529.89          | 69.18         |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 863.09            | 266.00            | 597.09            | 69.18         |
| <b>Nett Amount (S\$)</b>                         | <b>13,192.98</b>  | <b>4,066.00</b>   | <b>9,126.98</b>   | <b>69.18</b>  |
| <b>+ Loss of Use (5.0 x S\$120.00/day) (S\$)</b> |                   | 600.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                    |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>4,668.00</b>   |                   |               |

INSPECTION

|                             |            |                                                                                                            |
|-----------------------------|------------|------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 15/06/2022 |                                                                                                            |
| Date Inspected:             | 15/06/2022 | Inspected At: Sm Automotive - Kaki Bukit (HQ)<br>BLOCK C - 1, KAKI BUKIT AVE 6, #01-43<br>Singapore 417883 |
| Estimated Period of Repair: | 4.0 days   |                                                                                                            |

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's                                                 | Amount                         |
|-----|-----|----------|-------------------------------------|---------------|------------------------------------------------------------|--------------------------------|
| 1   | 1   |          | *REAR BUMPER                        | Deformed      | 889.10 FL                                                  | *889.10 FL                     |
| 2   | 1   |          | *REAR BUMPER SIDE RETAINER RH       | Damaged       | 230.79 FL                                                  | *110.00 FL                     |
| 3   | 1   |          | *REAR BUMPER REFLECTOR              | Cracked       | 121.30 FL                                                  | *121.30 FL                     |
| 4   | 1   |          | *RH REAR TAILLAMP                   | Cracked       | 789.10 FL                                                  | *635.00 FL                     |
| 5   | 1   |          | *RH REAR TAILLAMP APRON PANEL       | Deformed      | 389.10 FL                                                  | *389.10 FL                     |
| 6   | 1   |          | *RH REAR TAILLAMP APRON BRACKET     | Cracked       | 231.80 FL                                                  | *58.00 FL                      |
| 7   | 1   |          | *RH REAR FENDER                     | Repair        | 1,712.90 FL                                                | *- FL                          |
| 8   | 1   |          | *RH REAR FENDER INNER COWLING       | Torn          | 378.10 FL                                                  | *295.00 FL                     |
| 9   | 1   |          | *RH REAR FENDER STOPPER             | Necessary     | 43.20 FL                                                   | *43.20 FL                      |
| 10  | 1   |          | *RH REAR FENDER MUDFLAP             | Necessary     | 278.90 FL                                                  | *210.00 FL                     |
| 11  | 1   |          | *RH REAR WHEEL BEARING              | Not Necessary | 483.50 FL                                                  | *- FL                          |
| 12  | 1   |          | *REAR BUMPER REVERSE SENSOR RH      | Not Necessary | 380.00 FS                                                  | *- FS                          |
| 13  | 1   |          | *REAR BUMPER CLIPS                  | Necessary     | 80.00 FS                                                   | *30.00 FS                      |
| 14  | 1   |          | *RH REAR SPORT RIM                  | Not Necessary | 1,300.00 FS                                                | *- FS                          |
| 15  | 1   |          | *RH REAR TYRE                       | Not Necessary | 380.00 FS                                                  | *- FS                          |
| 16  | 1   |          | *RH REAR TAILLAMP APRON PANEL CLIPS | Necessary     | 50.00 FS                                                   | *20.00 FS                      |
| 17  | 1   |          | *RH REAR FENDER GLASS SEALANT       | Not Necessary | 120.00 FS                                                  | *- FS                          |
| 18  | 1   |          | *RH REAR FENDER SEALANT             | Not Necessary | 150.00 FS                                                  | *- FS                          |
| 19  | 1   |          | *RH REAR FENDER INNER COWLNG CLIPS  | Necessary     | 60.00 FS                                                   | *20.00 FS                      |
| 20  | 1   |          | *RH REAR BUILD SPOT SENSOR          | Cracked       | 1,817.90 FL                                                | *1,320.00 FL                   |
| 21  | 1   |          | *RH REAR BUILD SPOT SENSOR BRACKET  | Not Necessary | 121.40 FL                                                  | *- FL                          |
| 22  | 1   |          | *RH REAR BUMPER LOWER GARNISH COVER | Deformed      | 86.10 FL                                                   | *86.10 FL                      |
|     |     |          |                                     |               | <b>Sub Total (\$\$)</b>                                    | <b>10,093.19      4,226.80</b> |
|     |     |          |                                     |               | <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>1,893.30      1,039.20</b>  |
|     |     |          |                                     |               | <b>Total Parts (\$\$)</b>                                  | <b>8,199.89      3,187.60</b>  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                            | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                        |          |                 |                 |
| 1                               | LABOUR FOR PANEL BEATING                               | New      | 1,600.00        | 500.00          |
| 2                               | LABOUR FOR SPRAY PAINTING                              | New      | 1,400.00        | 700.00          |
| 3                               | WIRING CHECK                                           | New      | 80.00           | 30.00           |
| 4                               | LABOUR FOR REMOVE & REFIX RH REAR FENDER GLASS         | New      | 150.00          | 0.00            |
| 5                               | LABOUR FOR REMOVE & REFIX REAR UPHOLSTERY /ROOF LINING | New      | 300.00          | 60.00           |
| 6                               | TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS       | New      | 300.00          | 60.00           |
| 7                               | TO CALIBRE BLIND SPOT SENSOR                           | New      | 300.00          | 250.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                        |          | <b>4,130.00</b> | <b>1,600.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >