



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 5981G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,025.10	1,025.10
1	REAR BUMPER SIDE HOLDER RH (CONSISTENT)	CRACKED	78.90	78.90
1	REAR BUMPER REFLECTOR RH (CONSISTENT)	NOT NECESSARY	92.90	-
1	TAILLAMP RH (CONSISTENT)	CRACKED	781.40	781.40
1	TAILLAMP LOWER APRON RH (CONSISTENT)	DEFORMED	376.90	376.90
1	TAILLAMP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	697.40	-
	LESS 25% DISCOUNT		-	-565.58
			3,052.60	1,696.72
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	30.00
			50.00	30.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL RH.		500.00	300.00
	SPRAY PAINTING.		600.00	500.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
			1,250.00	880.00
GRAND TOTAL			4,352.60	2,606.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/ASM22005837/Avy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.