

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22005842/AGCY3E2**Date:** 03/11/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001862780
Claimant Vehicle No :	SMU2562S	Insured Vehicle No :	SNC1859B
Date of Loss:	18/06/2022	Nature of Claim:	TP
		Claim No:	276884

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU2562S		
Make & Model:	HYUNDAI ACCENT (RB), 1.4 5DR CVT ABS D/AB 2WD (A)	Engine No:	G4LCKU245385
Reg. Date:	04/08/2020 (Man. Year: 2019)	Chassis No:	KMHCU41BT KU481927
Colour:	Black	Odometer:	33979 km
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,471.30	4,071.76	4,399.54	51.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	2,530.00	1,300.00	33.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,301.30	6,601.76	5,699.54	46.33
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	12,301.30	4,600.00	7,701.30	62.61
+ GST 7.00/7.00% (S\$)	861.09	322.00	539.09	62.61
Nett Amount (S\$)	13,162.39	4,922.00	8,240.39	62.61

INSPECTION

Date of Assignment:	20/06/2022	
Date Inspected:	20/06/2022	Inspected At: ONE GARAGE PTE LTD (HQ) 8 KAKI BUKIT AVE 4 #03-33 PREMIER @ K. BUKIT Singapore 415875
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Nov 2022)

Parts: 143 HYUNDAI ACCENT (RB) 1.4 5DR CVT ABS D/AB 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMU2562S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Deformed	545.30 F	*545.30 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Damaged	89.60 F	*89.60 FL
6	1		*REAR BUMPER REFLECTOR	O/S Cracked	309.20 F	*154.60 FL
7	1		*REAR BUMPER REINFORCEMENT	Cracked	376.50 F	*376.50 FL
8	1		*REAR BUMPER REINFORCEMENT BRACKET UPPER	O/S Damaged	50.00 F	*25.00 FL
9	1		*REAR BUMPER REINFORCEMENT BRACKET LOWER (3PCS)	Damaged (1Pc Only)	75.00 F	*25.00 FL
10	1		*TAILLAMP	N/S Cracked	776.80 F	*388.40 FL
11	1		*TAILLAMP PANEL RH	Dented	278.40 F	*278.40 FL
12	1		*REVERSE SENSOR (4PCS)	Damaged (2Pcs Only)	740.00 F	*370.00 FL
13	1		*REAR END PANEL	Dented	499.30 F	*499.30 FL
14	1		*REAR END PANEL TOP GARNISH	Deformed	125.50 F	*125.50 FL
15	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
16	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
17	1		*BOOTLID	Dented	1,225.90 F	*1,225.90 FL
18	1		*BOOTLID LOCK	Damaged	175.40 F	*175.40 FL
19	1		*BOOTLID WEATHERSTRIPE	Cut	192.60 F	*192.60 FL
20	1		*HYUNDAI LOGO	Necessary	58.90 F	*58.90 FL
21	1		*ACCENT WORDING	Necessary	56.50 F	*56.50 FL
22	1		*REAR RH FENDER	Repair	1,703.20 F	*- FL
23	1		*REAR RH FENDER INNER TRIM	Not Necessary	255.60 F	*- FL
24	1		*REAR RH FENDER INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
25	1		*SPARE TYRE PANEL TOP COVER	Deformed	265.30 F	*265.30 FL
26	1		*TOOLS TRAY SPONGE	Not Necessary	159.80 F	*- FL
27	1		*REAR WINDSCREEN MOULDING	Not Necessary	152.50 F	*- FL
28	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
29	4		*REVERSE SENSOR HOLDER	Necessary	100.00 F	*100.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,471.30	5,062.20
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	990.44
Total Parts (\$)	8,471.30	4,071.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,500.00	1,200.00
2	SPRAY PAINTING	New	1,400.00	1,000.00
3	WIRING	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO SPRAY TUFF COAT	New	150.00	80.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
9	TO REMOVE REAR WINDSCREEN	New	180.00	0.00
Gross Labour Cost (\$\$)			3,830.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >