

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PB 555R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	AIR GUIDE TRIM (WCP)	NOT NECESSARY	200.00	-
1	ANTENNA (WCP)	NOT NECESSARY	55.00	-
1	FRONT SCREEN SPACER (WCP)	NECESSARY	40.00	40.00
1	GRILLE BADGE (WCP)	NOT NECESSARY	25.00	-
1	L/FR WIPER ARM (WCP)	NOT NECESSARY	70.00	-
1	L/WINDSCREEN MLDG (WCP)	NECESSARY	40.00	40.00
1	LWR WINDSCREEN SEAL (WCP)	NECESSARY	40.00	40.00
1	LWR W-SCREEN MLDG (WCP)	NECESSARY	40.00	40.00
1	R/DOOR MIRROR COVER (WCP)	NOT NECESSARY	250.00	-
1	R/FR WIPER ARM (WCP)	NOT NECESSARY	50.00	-
1	R/F SIDE PANEL (WCP)	DENTED	220.00	220.00
1	R/F WING MOULDING (WCP)	NOT NECESSARY	200.00	-
1	R/WINDSCREEN MLDG (WCP)	NECESSARY	40.00	40.00
1	UPP WINDSCREEN MLDG (WCP)	NECESSARY	40.00	40.00
1	WINDSCREEN (WCP)	NOT NECESSARY	550.00	-
1	WINDSCREEN BOND KIT (WCP)	NECESSARY	40.00	40.00
1	WINDSCREEN CATCH (WCP)	NECESSARY	40.00	40.00
	COST PLUS 15%		291.00	81.00
			2,231.00	621.00
	<u>LABOUR</u>			
	170.0 WU X 50.00 SGD/H.		850.00	790.00
	LABOUR COST 69.0 WU X 50.00 SGD/H.		345.00	345.00
	MATERIAL COST.		84.51	84.51
			1,279.51	1,219.51
	GRAND TOTAL		3,510.51	1,840.51

Report Ref No. CS/MSG22005847/Eqy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,450.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS/MSG22005847/Eqy3e2



Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser