

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005848/EQY3Q2**Date:** 28/11/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SNA00009072203

**Claimant Vehicle
No :** PC8885E**Insured Vehicle
No :** PC5017P

Date of Loss: 16/06/2022

Nature of Claim: TP

Claim
No: SNM22D204232/C02/CSC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **PC8885E**

Make & Model: ISUZU LT434P 7.8 SMT, 7.8 D (M)

Engine No: 6HK1694691

Reg. Date: 29/08/2017 (Man. Year: 2017)

Chassis No: JALLT434PH7000024

Colour: Multi-colour

Odometer: 323791 km

Engine Capacity: 7790 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	2,200.00	800.00	26.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	3,000.00	2,200.00	800.00	26.67

INSPECTION

Date of Assignment: 10/07/2022

Date Inspected: 22/06/2022 Inspected At:

Connect 3 (WOODLANDS) (HQ)
566 Woodlands Road (Mandai Estate)
Singapore 728697

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Nov 2022)	
Parts:	N/A	ISUZU LT434P 7.8 SMT 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC8885E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	600.00	300.00
2	SPRAY PAINTING WITH PEARL PAINT (MULTI COLORS AND DESIGN)	New	2,400.00	1,900.00
Gross Labour Cost (\$)			3,000.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >