



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 4501S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEEP CUT	980.20	499.80
2	FRONT BUMPER SIDE RETAINER @\$98.40	O/S BENT	196.80	45.00
1	FRONT BUMPER FOG LAMP COVER	NOT NECESSARY	196.20	-
1	FOGLAMP (RH)	NOT NECESSARY	425.60	-
1	HEADLAMP (RH)	CRACKED	1,655.50	1,199.00
1	HEADLAMP LOWER BRACKET (RH)	CRACKED	172.60	48.20
1	FRONT FENDER (RH)	NOT NECESSARY	845.20	-
1	FRONT FENDER INNER SHIELD (RH)	NOT NECESSARY	195.80	-
	LESS 20% DISCOUNT		-933.58	-358.40
			3,734.32	1,433.60
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	60.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	100.00	50.00
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	55.00	-
			215.00	50.00
<u>LABOUR</u>				
	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT.		80.00	20.00
	TO APPLY UNDERCOATING & RUST ROOFING.	NOT NECESSARY	100.00	-
	PANEL BEATING.		1,000.00	200.00
	SPRAY PAINTING.		800.00	300.00
			1,980.00	520.00
GRAND TOTAL			5,929.32	2,003.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CS/FCI22005849/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.