

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005851/RVY3Q2**Date:** 26/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00012702101
Claimant Vehicle No :	EQ1101L	Insured Vehicle No :	SLA4828E
Date of Loss:	23/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203797/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EQ1101L	Engine No:	A25A5197733
Make & Model:	TOYOTA CAMRY, 2.4 HYBRID (A)	Chassis No:	JTNB23HK703035249
Reg. Date:	07/11/2019 (Man. Year: 2019)	Odometer:	60257 km
Colour:	White		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,460.52	3,111.67	1,348.85	30.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,290.00	630.00	1,660.00	72.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,750.52	3,741.67	3,008.85	44.57
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	6,750.52	3,000.00	3,750.52	55.56
+ GST 7.00/7.00% (\$\$)	472.54	210.00	262.54	55.56
Nett Amount (\$\$)	7,223.06	3,210.00	4,013.06	55.56

INSPECTION

Date of Assignment:	20/06/2022	
Date Inspected:	24/06/2022 Inspected At:	Autosoon Pte Ltd (HQ) BLK 176 SIN MING DRIVE #01-10, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Sep 2022)
Parts:	143	TOYOTA CAMRY 2.4 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EQ1101L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE ASSY	Cracked	399.63 FL	*399.63 FL
2	1		*RADIATOR GRILLE ASSY SECURING CLIPS KIT	Necessary	50.00 FL	*50.00 FL
3	1		*RADIATOR GRILLE INNER GARNISH	Not Necessary	235.30 FL	*- FL
4	1		*BUMPER FACIAL	Deformed	552.65 FL	*552.65 FL
5	1		*BUMPER CLIP AND MOUNTING GROMET	Necessary	80.00 FL	*80.00 FL
6	1		*BUMPER SPONGE	Not Necessary	168.30 FL	*- FL
7	1		*BUMPER LOWER SPONGE	Not Necessary	135.30 FL	*- FL
8	1		*BUMPER LOWER GRILLE	Cracked	181.96 FL	*181.96 FL
9	10		*BUMPER LOWER GRILLE CLIP	Necessary	80.00 FL	*80.00 FL
10	1		*O/S BUMPER RETAINER ASSY	Cracked	131.68 FL	*131.68 FL
11	1		*O/S PARKING SONAR SENSOR ASSY	Not Working	396.24 FL	*396.24 FL
12	1		*O/S PARKING SONAR SENSOR BEZEL	Not Necessary	36.53 FL	*- FL
13	1		*O/S HEAD LAMP ASSY	Scratched	2,208.74 FL	*2,208.74 FL
14	1		*O/S HEAD LAMP LOWER STAY	Cracked	68.00 FL	*68.00 FL
15	1		*O/S HEAD LAMP SUPPORT PANEL	Not Necessary	231.80 FL	*- FL
					Sub Total (S\$)	4,956.13
					- List Item Discount on L Items 10.00/25.00% (S\$)	495.61
					Total Parts (S\$)	4,460.52
						3,111.67

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REWIRE AFFECTED SECTION AND REFOCUS HEAD LAMP BEAM	New	80.00	30.00
2	TO PUTTY AND RESPRAY AFFECTED SECTION IN REPAIR	New	880.00	250.00
3	TO UNDERSEALING DAMAGED PANELS WITH ANTI RUST	New	150.00	0.00
4	TO REMOVE AND REPLACE DAMAGED PART ,PANEL BEAT RADIATOR SUPPORT AND HEAD LAMP PANEL INCLUDE REALIGN BUMPER IN REPAIR	New	680.00	250.00
5	TO USE TOYOTA COMPUTER PLATFORM TO CHECK /GO ON LINE TO ACTIVATE MILLEMMETER RADAR AND PARKING SONAR SENSOR	New	500.00	100.00
Gross Labour Cost (\$)			2,290.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >