

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22005855/VVY3Q2**Date:** 29/08/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** GBH2858M **Insured Vehicle No :** SMG4222J

Date of Loss: 15/06/2022 Nature of Claim: TP Claim No: DMCF2200096H/02/JT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH2858M**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: D4CBH296235

Reg. Date: 09/04/2018 (Man. Year: 2017) Chassis No: KNCSJX76LH7186915

Colour: White Odometer: 75583 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6 mm

Front Right Side: Triangle 6 mm Rear Right Side: Triangle 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,399.60	509.20	890.40	63.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	990.00	440.00	550.00	55.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,389.60</b>	<b>949.20</b>	<b>1,440.40</b>	<b>60.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>750.00</b>		
<b>Nett Amount (S\$)</b>	<b>2,389.60</b>	<b>750.00</b>	<b>1,639.60</b>	<b>68.61</b>

INSPECTION

Date of Assignment: 20/06/2022

Date Inspected: 23/06/2022 Inspected At: HANG KHIANG MOTOR WORKSHOP  
Blk 3012 Bedok Ave 4 #01-2042 Bedok Ind Pk E  
Singapore 489978

Estimated Period of Repair: 4.0 days

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 29 Aug 2022)	
<b>Parts:</b>	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH2858M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LOWER PANEL	Dented	599.00 FL	*599.00 FL
2	1		*REAR LAMP LH	Not Necessary	144.00 FL	*- FL
3	1		*REAR LAMP PANEL	Not Necessary	132.00 FL	*- FL
4	1		*REAR TAILGATE	Repair	677.00 FL	*- FL
5	1		*REAR TAILGATE 70 KM STICKER	Not Necessary	10.00 FS	*- FS
6	1		*REAR TAILGATE 13 PAX STICKER	Not Necessary	10.00 FS	*- FS
7	1		*REAR TAILGATE KAO LEE STICKER LH	Not Necessary	108.00 FS	*- FS
8	1		*REAR NO PLATE	Bent	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,710.00</b>	<b>629.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	310.40	119.80
<b>Total Parts (\$\$)</b>	<b>1,399.60</b>	<b>509.20</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE CUT OUT DAMAGED PORTION ,JACK OUT STRAIGHTEN ,PANEL BEATING ,WELDING ALIGN AND RENEW REPLACE PARTS	New	480.00	400.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	400.00	0.00
3	TO CHECK WIRING AND LIGHTING	New	30.00	0.00
4	TO ANTI RUST ON AFFECTED AREAS	New	80.00	40.00
<b>Gross Labour Cost (\$)</b>			<b>990.00</b>	<b>440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >