

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMG 4222J

Policy No. _____


Claims No. DMCF2200096H/02/JT

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 50k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH2858m Yr Regn: 9/4/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nia N2500 c.c. 2497Colour: White A/C: Insured / Std / NI / NASp. Reading: 75583 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNCS5776LH7186915Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15CR: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or triangleFront R/Bal. 6 mm Rear R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15/6/22 D.O.I. 23/6/22 1400Survey held at Hang KhungDes. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 50krebate: 13844NV: 3615697378398 William

26/8/22 LS \$750 (un-confirmed)

7/11/22 Bryan contacted William, ask whether can reduce to 1500 - 1600.22/10/22 Bryan informed repaired LS 1500/4 days (reel 88960, 377)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 26/8/22-typist

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL



HANG KHIANG MOTOR WORKSHOP

BLK 3012, BEDOK INDUSTRIAL PARK #01-2042,
BEDOK NORTH AVE 4 SINGAPORE 489978.

TEL: 64412274 FAX: 64421944

Reg No: 341403/00Lwed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TO: ECCS Insurance

Acknowledged by Repairer

Signature:

Date:

Date: 23/6/2022

Estimated cost of repairs vehicle no. 6BH 2858M

Parts Supply

- 1 Pc. rear bumper lower panel
- 1 Pc. rear lamp Lh Ht Dim
- 1 Pc. rear lamp panel Ht Vst
- 1 Pc. rear tailgate Lh

List Items

- # 599.00 - DT
- 144.00 - CRG ✓
- 132.00 - BT ✓
- 677.00 - MDT X

1,552.00
310.40
1,241.60

Less 20%

S. Net

- 1 Pc. rear tailgate "70" KM sticker Ht
- 1 Pc. rear tailgate "13" PAX sticker Ht
- 1 Pc. rear tailgate "KAO LEE" sticker Ht
- 1 Pc. rear no. plate

- 10.00 - Ht
- 10.00 - Ht
- 108.00 - Ht
- 30.00 - BT

Labour charges

To remove, cut out damaged portion, jack out, straighten, panel beating, welding, align and renew replace parts.

480.00
480.00

To putty and respray painting on affected areas. Ht 400.00 ✓

Ht 30.00 / 80.00
80.00 40

To check wiring and lightings.

To anti rust on affected areas.

Total # 2,389.60

F: L/S/800

RP: 4